

20 GU

LIVRET D'AERONEF
AIRCRAFT LOG BOOK

AÉRONEF - AIRCRAFT

1. Marques de nationalité
et d'immatriculation :

1. Nationality and
Registration Marks :

20 GU

2. Classification
2. Classification
Catégorie :
Category :

Voir Certificat de Navigabilité

Annotations — Mentions d'emploi : Sans Objet
Subdivision :

3. Type de l'aéronef :

3. Aircraft type : SOCATA TB 20

n° de série :

Serial No. : 655

4. Construction par :

SOCATA

4. Maker, place and date of construction :

le 06/1986 à OSSUN
on at

Livret établi à
Log Book established at

PARIS le
on
(Place and date)

01/07/86

BUREAU VERITAS (Signature et Cachet)
Signature and stamp of Issuing Authority,
Bureau Veritas



BRANCHE AERONAUTIQUE
Le Directeur

[Signature]

X

MODIFICATIONS APPORTÉES A L'AÉRONEF - AIRCRAFT MODIFICATIONS EMBODIED

Date Date	Détails des modifications Références aux décisions d'approbation Particulars of modification and Approval Authority	Visa Signature
5/19/90	Tach. 306.57 Installed Fuel Check Valve Kit # 9121	AP 1844079 
6-29-90	EACH READS 39.14 hrs. INSTALL FUEL TANK KIT Nr. 9154	

[illegible]

[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

1

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
socata STATEMENT TARBES Altimeter/Static and altitude reporting equipment systems have been tested and inspected per appendices E and F of part 43, as required by F.A.R. 91.171, Calibrated to Dated <i>June 18, 1986</i> Signed <i>[Signature]</i>		U.S. STANDARD AIRWORTHINESS CERTIFICATE ISSUED ON <i>2 JUL 86</i> INSTALLED IN AIRCRAFT ON BEHALF OF F.A.A. (ALU 100) ON <i>2 JUL 86</i> 
socata STATEMENT TARBES Transponder has been tested and inspected and found to comply with appendix F of Part 43 in accordance with FAR 91.172. Dated <i>June 18, 1986</i> Signed <i>[Signature]</i>		

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

2

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
7/27/87	Reassembled aircraft I/A/w TB-20 Maintenance Manual	<i>J. Struble</i> 1910203
7/28/87	SB 30 main landing gear boxes stiffeners Installed as per Socate Technical Instructions No. 9130 See 337 This date	<i>Clarence R. Burlew</i> IA 1950494
7/29/87	I certify this Aircraft S/N 655 model TB-20 was inspected in accordance with an Annual Inspection and found Airworthy	<i>Clarence R. Burlew</i> IA 1950494
7/29/87	Test Flight required for Reassembly of Aircraft and a Annual Inspection	
7/30/87	Test Flight completed following reassembly & Annual inspection. Aircraft found Airworthy	<i>J. Struble</i> 1381338

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

3

Dates	Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
1-5-57		Test Hours 31.44 INSPECTED FRAME #9 IAW SERVICE BULLETIN #35 NO FAULTS FOUND AT THIS TIME.	<i>[Signature]</i> ATP 567 04 900
8/10/58		TACH. 80.91 HRS. Replaced all Brake Pads, Replaced left main tire, performed RETRACT TEST of Landing Gear, Lubed all hinge points, Normal and emergency extension satisfactory (5 times) Replaced landing light, Lubricated all hinge points and Flight Controls. Complied with all AD's - see RECORD in REAR of LOG. Complied with SOCATA SERVICE BULLETINS - Nr 28 Aileron Balancing by Inspection (Para A), C/W Nr 29 STABILIZER CONTROL ROD PAR PARA. B, Replaced CONTROL ROD Assy. — C/W Nr 33 HYDRAULIC BRAKE LINE ATTACHMENTS by installing SOCATA KIT # 9139 - OVER-	

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
				Report Brought forward .					
				C/w Nr 34. LANDING GEAR Hydraulic Line by REPLACEMENT of Line Per Kit # 9137. C/w Nr 35/i HORIZONTAL STAB ATTACHMENT PER TAA Inspection of FRAME 9. No CRACKS FOUND. Tach Time <u>80.91 hr</u> Total Time <u>80.91 hr</u> I certify that this aircraft/engine has been inspected in accordance with a <u>ANNUAL</u> inspection & was determined to be in an airworthy condition. Pertinent details are on file at this agency under Work Order No. <u>9806</u> Date: <u>8/10/88</u> Signed <u>D Edwards</u> LA 1179255 for TOPP OF TAMPA AIRPORT, INC.					
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

4

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
8/10/88	TACH: 80.91 Removed Altimeter & installed servicable one. I certify that the static pressure system, each altimeter instrument, and each automatic reporting system tests and inspections required by FAR 91.171 have been performed. 1. The static pressure system was tested on <u>7/13/88</u> 2. The altimeter instrument was tested to <u>20,000 ft.</u> on <u>7/13/88</u> (pilot/co-pilot) 3. The automatic pressure altitude reporting system was tested to <u>ft.</u> on <u>7/13/88</u> Signature <u>Curtis B. Mitchell</u> Certificate No. <u>197486021 A+F</u>	
8/13/88	TACH 81.39 hr. Replaced Landing Gear Hydraulic Generator - Jacked A/C and Performed Satisfactory RETRACT TEST. R.D. Radford A/P 577688606	

depuis fabrication :
Since manufacture

SERVIC

able Part

Dates	Détails vérifications et travaux entret Modifications —	Organisme de contrôle
Date	Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Stamp and signature of overhauler and of controlling Authority
2/15/88	Tach 1282hr ² Adjusted idle mixture, Removed and Reinstalled Directional gyro, Complied with AD 87-22-02 and Secata Service Bulletin 35/1 "Horizontal Stabilizer Attachment Flange" by Installation of OIT 9145 kit. — Russell D. Rucker AEP577689606	
10-4-89	TACH TIME 196.19 REPLACED ECT BATTERY WITH NEW PART INSTALLED 4 NEW STATIC WHIPS REMOVED FUEL PUMP DUKES PUMP OVERHAULED BY FAN REPAIR STATION # KB209464 REPLACED FUEL PUMP JAW, SM REMOVED ALL ACCESS PANNES LUBED ALL CONTROLS REPLACED ALL PANNES, SERVICED BATTERY REMOVED Trim Jack SCREW CLEANED LUBED AND RE INSTALLED JAW, SM CW ALL AD'S CHECK THREW 89-15-10 GROUND CHECK ALL SYSTEMS IN THE GREEN. — END —	
	Anthony R St George AEP 246222817	

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
T.T: <u>196.19</u> TACH READ <u>196.19</u>				Report Brought forward .					
CERTIFY THAT THIS <u>AIRCRAFT</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>ANNUAL</u> INSPECTION AS WAS DETERMINED TO BE IN AIRWORTHY CONDITION.									
<u>10-4-89</u> <u>Anthony R. St. George</u> DATE SIGNATURE A.I. NO. <u>266922817</u>									
<u>4-27-80</u> Tach time <u>300.0</u> <u>CW AD</u> <u>90-02-18</u> BY INSALATION OF <u>WELDON PUMP</u> <u>fit</u> <u>9156-9132</u> <u>INSPECTION</u> <u>ACCOMPLISHED IN ACCORDANCE WITH ASSEMBLY</u> <u>INSTRUCTIONS # 644.00</u> <u>AIR CRAFT TEST</u> <u>FLOWN THIS DATE ALL SYSTEMS WITH IN LIMITS</u> <u>AIP 266826844</u> <u>Sh</u> <u>Long</u>									
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

6

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
5-19-90	Tach. 306.57 Installed fuel check valve kit #9128. Run engine checked for leaks ok.	<i>J. Charbon</i> AP 1844074
5-25-90	Tach 307.12 Installed new actuating cyl. Right main gear. Retraction ✓ performed as per service manual. Checked for leaks ok. See attached service tag	<i>J. Charbon</i> AP 1844074
6-29-90	TACH 319.14 hrs. Installed KIT No. 9154, FUEL TANK MODIFICATION DRAINED AND SEALED ALL SENDING UNIT FLOATS. R+R RH TIRE AND BRAKE PADS. ALSO REPLACED LH. FUEL LINE (TANK TO FUSELAGE) P/N TB20.52.000.00 3(2). FILLED AK WITH FUEL NO LEAKS EVIDENT, A/C TEST FLOWN.	<i>Chen Mark</i> AP #314662861 I.A.

ALT SCALE ERROR TOL
-1000 300

ALT FRICTION
1000

TOL
70

FT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Arrivée Departure Arrival		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
9-25-90				Report Brought forward.					
FAR 91.171 ALTIMETER(S). ALTITUDE REPORTING EQUIPMENT AND STATIC PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E OF PART 43. ALTIMETERS(S) CERTIFIED TO LT <u>20,000</u> FEET. RT. <u>1121</u> FEET DATE <u>9-25-90</u> NO# <u>1121</u> SIGNATURE <u>[Signature]</u> FLIGHTLINE AVIONICS INC. 2793 Flightline Ave. Hangar 4 Westside Sanford, FL 32773 CRS# <u>FXQR922K</u>				The ATC transponder tests and inspections required by FAR 91.172 were performed on this date and found to comply with FAR 43, Appendix F. Transponder #1 <u>S/N</u> Transponder #2 <u>S/N</u> Details of this inspection are on file at Repair Sta. 764-117. NO# <u>1121</u> Dated <u>9-25-90</u> Signature <u>[Signature]</u> INSP <u>FXQR922K</u> FLIGHTLINE AVIONICS INC. 2793 Flightline Ave. Hangar 4 Westside Sanford, FL 32773 CRS# <u>FXQR-922K</u>					
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

7

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

29-00 TACH READ 319, 14 hrs. at 23:12Z 6/1

~~Task 6 - Nr. 9154 - Ch. M. d. 10. 10. 1984.~~

1-4-90 TACH READS 383.8 hrs. TTS NEW Annual Inspection Complete

Lubed and inspected entire aircraft per SoATA Inspection
Guides. Replaced vacuum regulator filter, all brake pads,
and locking washer on LH main gear axle nut. Replaced
nose tire and LH main gear tire, packed all wheel bearings.
Removed corrosion from shock strut (LH) upper piston. Wiped
all exposed pistons with hydraulic fluid. Gear retraction test
performed, emergency extension complete found ok.
Checked hydraulic reservoir, ok. Checked A.O's thru 90-10.
ELT operation checked, ok. Battery due-AUG 91-.

1. I CERTIFY THAT THIS FILE HAS BEEN

INSPECTED IN ACCORDANCE WITH AN ANNUAL

INSPECTION AND WAS DETERMINED TO BE

IN AIRWORTHY CONDITION. T.T. 383.8 hrs.

SIGNED

-LIC.#

DATE _____

AD #314662861A

11-4-90

SERVICE DE L'AÉRONEF • AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Depart- ure	Arrivée Arrival				
				Report Brought forward .					
2-21-91	YACH	READS	432.9 hrs.	Installed new master switch AREA placard. Replaced missing splice discharges wires. On ST Hook A-P#314662861					

MODEL TB-20
S/N 655
REG. NO. N20GU

ORLANDO

AVIONICS CORP.

FAA APPROVED REPAIR STATION #TPARSS2M
P.O. BOX 140741 • ORLANDO, FLORIDA 32814
TELEPHONE: (407) 854-9563

DATE 12-8-89
T.T. 200
HOUR/M

Installed 3M WX-1000 Stormscope system in right
hand instrument panel. See FAA Form 337 dated
12-8-89 for further details.

J. W. Jeff

A reporter
Carried forward.

Durée totale des vols : depuis dernière R.C. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

8

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
3-25-91	TACH READS: 457.0 hrs. Installed new window in pilots door. C/w A.D. 91-05-02 Lower Firewall inspection, found OK per S.B. Nr. 42/1, next inspection due at 957 hrs. TACH TIME. C/w S.B. Nr. 55 Engine air inlet filter, found correct type installed (BAT 112). Chris D. Mock ACP# 34662861	
5-8-91	TACH READS 471.44 C/w A.D. 90-25-17 OIL COOLER INSP. BY VISUAL MEANS. C/w S.B. NR 57 IAW S.B. NR 57, INSTALLED NEW WASHERS + SELF-LOCKING NUTS, SPOT. PACKED WEIGHT/MINIMUM WT. CHANGE. THREAD ENGAGEMENT OK. Doug P. Hart ACP 044-50-9848	
6-12-91	Removed and Replaced Prop Control Cable TB 20-57-005-002	
6-12-91	Removed Interphone system. Installed Teler PC-4 intercom with Music input. Installed Vario com adapter. No A+B changes.	CARROLL AVONICS, INC. WESTERLY AIR SERVICE BLDG. STATE AIRPORT WESTERLY, RI 02891 E. Carroll 2377609 FAA REPAIR STATION UQ 5R 258 N

[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

9

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
---------------	---	---

Airframe

LOG BOOK ENTRY

A/C REG: N20GU

A/C S/N: 655

DATE: 8-23-91

A/C TOTAL TIME:

HOURLY METER: Tach: 537.

W/O NO: 4875

ENGINE TOTAL TIME

S.M.O.H.

1. Replaced the Plastic Floats in both right wing fuel senders and ~~one inboard~~ left wing fuel senders. Resealed the fuel senders with new fuel gaskets and sealant. Leak check completed satisfactory.
2. Removed and replaced the aileron support arm, P/N TB10.11.003.005 in accordance with SOCATA Maintenance Manual instructions.

MAINTENANCE RELEASE

THE AIRCRAFT AIRFRAME, ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED. PERMANENT RECORDS OF THE REPAIR ARE ON FILE AT THE REPAIR STATION UNDER WO # 8-23-91 DATE 8-23-91 SIGNED [Signature]
FOR COLUMBIA AIR SERVICES, INC. FAA CERTIFIED REPAIR STATION # S05R204N GROTON, CT 06340

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

10

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

91-15-10
CW AD 91-12-19 EAW 54 TB 57 by Inspector
Horizontal Stab. Balance weight

I certify that this aircraft
has been inspected in accordance with
Annual inspection and found
to be in airworthy condition.
12-12-91 562 HAC

John Smith
FA 373 41 529

ATC TRANSPONDER TESTS AND INSPECTIONS
REQUIRED BY FAR 91.413 WERE PERFORMED
ON 10-02-92 AND FOUND TO COMPLY WITH FAR
PART 43 APPENDIX F.

INSPECTOR *[Signature]* WORK ORDER A11632

MAKE KING MODEL KT76A

SERIAL 47373

VIP AERO
INSTRUMENTS & AVIONICS
BRAINARD AIRPORT
HARTFORD, CT 06114
FAA REPAIR STATION
NO. TH5R223N

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Arrivée Departure Arrival		Durée du vol Duration of Flight	Kilo- mètres parcours Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atter- rissage Number of Landings
FAR 91.411 HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH PART 43 APPENDIX E PARAGRAPH XOXO THIS ALTIMETER HAS BEEN TESTED TO 20,000 FEET AND FOUND SATISFACTORY FOR RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS FACILITY. INSPECTOR <u>[Signature]</u> WORK ORDER <u>A11632</u> MAKE <u>PR</u> MODEL <u>IPK45-20</u> SERIAL <u>011</u> DATE <u>10-23-92</u>				Report Brought forward.					
VIP AERO INSTRUMENTS & AVIONICS BRAINARD AIRPORT HARTFORD, CT 06114 FAA REPAIR STATION NO. TH5R223N				ATC TRANSPONDER TESTS AND INSPECTIONS REQUIRED BY FAR 91.413 WERE PERFORMED ON <u>10-23-92</u> AND FOUND TO COMPLY WITH FAR PART 43 APPENDIX E INSPECTOR <u>[Signature]</u> WORK ORDER <u>A11632</u> MAKE <u>KING</u> MODEL <u>KT76A</u> SERIAL <u>47373</u>					
AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM TESTED TO <u>20,000</u> FEET AS REQUIRED BY FAR 91.411 IAW FAR 43, APP. E, PARA. G. INSPECTOR <u>[Signature]</u> WORK ORDER <u>A11632</u> MAKE <u>WALCO</u> MODEL <u>1AR-850</u> SERIAL <u>11257</u> DATE <u>10-23-92</u>									
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

11


Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

12-04-92 CERTIFIED STATIC SYSTEM PER FAR 21.413 IN ACCORDANCE
WITH FAR 43 APPENDIX E, PARA. A



INSTRUMENTS & AVIONICS
BRANARD AIRPORT
HARTFORD, CT 06114
FAA REPAIR STATION
NO. TH5R223N

1-11-93

AIRFRAME-Jacked aircraft, removed wheels, greased bearings & gear, checked brakes, checked retraction & emergency extension. Checked electrical system & battery. Checked all controls & oiled as needed. Removed all inspection plates & checked structure. Checked cockpit, belts, seats, lights & instrument operation.

733.65

733.65

Replaced Both Main Landing gear Brakes

Disks pn 164-01900 and all Brake linings pn

66-106 Replaced Carb Air Inlet Filter CVAU

91-12-19 on Elev control weight by inspection

Tightened Bolt on GN Gear Door Attach Checked AD

Compliance See AD History Book of log book

certify that this aircraft-

has been inspected in accordance with

Annual inspection and determined

to be in satisfactory condition

Date 1-11-93 Time 733.65

FA 373 41 529

1-16-93

Installed Graphic Engine monitor and Precise Flight Vacuum pump & prop warning light See FAA Form 337 this Date

EW 1884

New CG 38.3 New useful load 1213

FA 373 41 529

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings		
				Départ Departure	Arrivée Arrival						
				Report Brought forward.							
5-12-93	TACHÉ TOTAL	752.2	Installed Dactron outside air temperature Indicator in accordance with manufacturer installation instructions complete and file per 337 - Michael A Benoit 1A015389017								
9-15-93		765.1	C/w AeroSpecial S/b #52 by Removing LT & RT Fuel Tank Access Panels Cleaned Area of Sealant & Reson with Proper Sealant (PR1403G) as instructed in Service Bulletin. Walter M... A/P 1422624								
				A reporter Carried forward.							

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

12

Date
Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

11-7-93 TACK 806.61 SERVICED AND INSTALLED NEW BOTTLE
PROVIDED BY OWNER Robert C. Chena AP395384005

N20GU Tach 831.6 Work Order# 17156

Removed Northstar M1 system. Installed Northstar GPS600 with AT575-9 antenna. All work done I.A.W. AC43.13-1A chapters 11, 13, & 15, AC43.13-2A chapters 1, 2, & 3, and manufacturers instructions. GPS is placarded for VFR only. Functional check satisfactory.

New empty weight	1884.5
New E.W.C.G.	38.3
New moment	72145.2
New useful load	1212.5

Walter Chena 1/6/94
the radio shop inc. airport worcester, ma 01602
FAA Repair Station TD5R219N

Since manufacture

Total flying time since last major overhaul

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Departure Arrivée Arrival		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- mètres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
2-24-94	TACH TOTAL	837.	4 Opened all inspection panels, wiped all control surfaces and attach points. Replaced Left outboard elevator trim tabs. Replaced Pin P/N TB20.34.001.114 and 0115. Replaced Pin P/N TB20.34.001.117 Pin. Replaced E.C.T. battery, new battery replacement data is 2-96 A.D. List in rear of AIF logbook.	Report Brought forward.					
				Inspection of this Aircraft N2004 has been inspected in accordance with the ANNUAL inspection and found to be in airworthy condition. Michael A. Bernier 2-24-94 Signature Authorization 013003017					
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
6-22-94	TACH 856.0 Removed and replaced windshield assembly with O.E.M. Part. Sled and Seams windshield in place. — Michael A. Benin ATP015389017	
8-19-94	TACH 875.0 Removed and replaced nose gear tire and Left main tire. — Walter Irone H#81422624	
0-13-94	892.0 Complied with Service bulletin #47 on lubrication of all landing gear articulated Step. — Michael A. Benin 015389017	

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
				Report Brought forward.					
N20GU Tach 894.7 Work Order# 17962 FAR 91.411 has been accomplished I.A.W. Part 43 Appendix E, Paragraph A,B,C. The altimeter has been tested to 20000 feet. Altimeter: IFR IFR45-20 #011 Encoder: Narco AR-850 FAR 91.413 has been accomplished I.A.W. Part 43 Appendix F. Transponder: King KT-76A #47373 <i>Robert Choma</i> 10/20/94 the radio shop inc. airport worcester, ma 01602 FAA Repair Station TD5R219N									
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

14

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
3-15-95	TACI & TOTAL 937.9 Opened all Inspection Panels Inspect control surfaces and attach points, lubricate as required. Replaced all main gear brake linings. Service and charge aircraft battery. Complied with AD 91-05-02 on inspection of fuselage and Landing Gear attach area. S.S. Inspected S.O.A.R.S. Landing Gear retraction, normal and emergency. Service Hydraulic reservoirs. Landing Gear and Brake system. Complete AD list in rear of the logbook.	<i>[Signature]</i>
<i>[Signature]</i>	I certify that this Aircraft <i>N2064</i> has been inspected in accordance with a <i>Annual</i> inspection and was determined to be in airworthy condition. <i>Michael A. Bower</i> Date <i>3-15-95</i> Inspection Authorization <i>016339017</i>	<i>[Signature]</i>

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Arrivée Departure Arrival		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
4-12-96 TACH of total 1043.1			Opened all Inspection Panels and Inspect all Control Surfaces and attach paint. Removed and replaced E.L.T battery and Inspect ELT as per 91.207(c) new battery replacement date is 2/98. Removed and replaced all (4) fuel Sender units and Gaskets. Perform landing Gear retraction test manual and emergency, found OK. Service Hydraulic reservoir and brake reservoir.	Report Brought forward . THIS AIRCRAFT HAS BEEN INSPECTED AND WAS DETERMINED TO BE IN AIRCRAFT CONDITION. Walt Moore N74226 VIX					
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

ETIQUETTE D'IDENTIFICATION
INSPECTION TAG
PIECES REVISÉES
930 - 65009 TARBES CEDEX
CUSTOMER SUPPORT
DIRECTION SURVEILLANCE

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature répar. Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
5-3-96	1043.8 Replaced Left Side Interior fuel Line assembly	PIN TB20-52000005 Walter J Moore AEP1422624
5-29-96	TACH. 1059.1 Removed and Replaced Avionics Firewall assembly, used manufacturer Supplied Part. #TB21.24601101 also replaced fuel Pump Circuit Breaker/Switch.	Walter J Moore AEP1422624
7-12-96 TACH. 1063.14	Complied with Service bulletin #47 by Installing Kit #OPT10916500 on More Gen and Kit # OPT10916600 on each main Gen. Before Ground Operational test, fuel OK.	Walter J Moore AEP1422624

Carried forward.

Since manufacture
reports fabrication

Total flying time since last major overhaul

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
10-24-96	TKA 1089.3			Report Brought forward.					
Removed and Replaced Landing Gear with Overhaul Exchange unit. See Balance rods (2) PIN 200N7070110709. Perform Operational Test of Landing Gear. Normal and Emergency all good. OK.				Hydraulic Power Pack PIN 422624					
				Walter J. Moore					
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

the radio shop inc. airport worcester, ma 01602
FAA Repair Station TD5R219N

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD


Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcours Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
4-18-97				Report Brought forward.					
TACH. 1114.3. TOTAL				Opened all Inspection Panels and inspect Control Surfaces and attach Points. Replaced all Right main Gear Brake lever. Cleaned and lubricated all Brake Pins. Inspect F.L.T. as Per 91.207(d) Battery Replacement Date in 2-98. Replaced Nose Gear Tire and Left main tire. Perform Operational Test of Landing Gear Normal and Emergency. Service Hydraulic reservoir. I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AIRM 9001/1 INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. Wally Moore N422624 JA					
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

17

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
6-10-97 TACH. 1124.29	Removed and Replaced Inboard left and Right elevator Train Tie hinge and hinge pin assemblies also and pin assemblies. also replaced Propeller bearing in all parts Supplied by manufacturer	rudder trim tab hinge Governor and rod Michael A Bruner 015385017
12/3/97 TACH: 1174.4	R+R Landing light bulb #4509. Lynn	
2/21/97 TACH 1191.0	R+R 4(FOUR) BROKEN STATIC WICKS. REPLACED WITH 4 NEW WICKS. SOCATA PART # TB20-61911001 R+R PASSENGER SIDE DOOR SEAL. REPLACED WITH NEW SEAL SOCATA PART # 200.N4241491604 Larry Lynn	4 NEW WICKS.
4/10/97	 LOG BOOK ENTRY ELT BATTERY REPLACEMENT DATE 5/00	Replaced ELT battery w/ Narco 2 year. Tested O.K. Due again 5/00 Larry Lynn

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcours Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
4-21-98	TCH 1202.9			Report Brought forward.					
			Complied with AD 98-04-03 by Installation of Rot as per Soeda Service Bulletin SB 10-103. Walter Moore NRP 1422624						
				A reporter Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SOCATA AIRCRAFT
North Perry Airport
Pembroke Pines, Florida
FAA Approved Repair Station URZR891L

May 8, 1998

S/N 655

N 20GU

Tach.1212.06

W/O # 1207

1. Installed left and right sun visor support bracket P/N ZOON7788014136.
2. Replaced L/H cabin interior's snap buttons with new P/N ZOON7079745171.
3. Replaced flap position printed circuit P/N TB20 61095000.
4. Replaced flap position indicator P/N TB20 61097002 Ops checked good.
5. Replaced L/R instrument panel faceplate snap buttons P/N ZOON7193144404 and ZOON7193144402.
6. Replaced co-pilot brake master cylinders P/N ZOON6043077221, bled brake, and leak checked.
7. Replaced parking brake "O" rings per Kit No.199-527 leak checked OK.
8. Replaced loose rivets on rudder lower attachment bracket by bolts and nuts per Kit # OPT10 9126 per SOCATA Technical Instruction # 9126.
9. Replaced L/R wing root seals P/N TB1009130102.
10. Replaced 5 broken head rivets on right wing trailing edge next to flap inboard end.
11. Replaced L/H brake linings P/N ZOON7313730000.
12. Replaced broken nose gear stop block P/N ZOON7103702301.
13. Replaced all 3 brake reservoir gaskets P/N ZOON7423527101.
14. Replaced L/H step P/N TB1028007006.
15. Temporary removed NARCO ELT Transmitter S/N A30058 for inspection, placard stating ELT NOT INSTALLED is displayed in clear view of the pilot.
16. Replaced landing gear emergency valve's "O" rings P/N ZOON7423070720, gear cycled and leak checked OK.
17. Replaced 6 intake pipe adapters P/N 69603.
18. Replaced 6 intake gaskets P/N 71973.
19. Replaced corroded static discharge hardware with new.
20. Installed L/H door gas rod lock cap P/N ZOON5730002060.
21. Installed baggage loading limit decal P/N TB1072048100.
22. Replaced corroded rivets in L/R wing spar area.
23. Cleaned off corrosion and treated see attached discrepancy sheet for details.
24. AD 87-22-02R1 Visual inspection for cracks at frame No.9 found OK.

Continued next page.

Airframe continued

25. C/W AD 90-25-17 Visual inspection of engine oil cooler found OK.
26. C/W AD 91-15-10 Visual inspection of Horizontal stabilizer balance weight found OK.
27. C/W AD 93-02-05 Visual inspection of fuel injection lines found OK.
28. C/W SB 10-042/1 Visual inspection for cracks on frame No.0 firewall found OK.
29. C/W SB 10-044 Visual inspection of front seat belt lower attachments found OK.
30. C/W SB 10-049 Visual inspection for cracks of console side on frame No.0 found OK.
31. C/W SB 10-058/1 Visual inspection of catches on cabin access doors found OK.
32. C/W SB 10-067 Fuel tank air vents system, replaced vent hoses per instruction in SB.
33. C/W SB 10-071 Rudder balance weight found corrosion between weight and skin, cleaned, treated, applied Mastinox and reinstalled per instruction in SB.
34. C/W SB 10-084 Inspection of wing ribs, fuel tanks area found no defect.
35. C/W Lyc.SB 518C, found N/A by S/N, Thermostatic bypass valve installed is P/N 75944 S/N 221283.
36. Removed and reinstalled rudder per M/M chapter 55-40 for lower attachment bracket Modify see Item 8.
37. Replaced vacuum filters P/N ZOON7284010901/B3-5-1.
38. Replaced Manifold inlet filter P/N ZOON7284480058.
- Airframe, Engine, Propeller and Appliances ADs researched through Rev.98-09 see AD compliance report.
- List of discrepancies did not corrected at this time selected by aircraft owner has signed and provided to the aircraft owner.

I certify that this Aircraft has been inspected in accordance with an annual inspection per FAR 43 Appendix D and was determined to be in airworthy condition.

C/W. SB. 10-092 Application of Anti-Corrosion Protection.

I certify that this Aircraft/Engine/Propeller/
Appliance has been inspected/repared in
accordance with an ANNUAL
Inspection and determined to be in Airworthy
condition. Permanent details on file under
W/O# 1207 and copy given to customer.
Acft. T.T. 1212-06
Engine T.T. 1212-06 Date 5-8-98

Signature H. Phomphavath
CRS-URZR8911.

Required functional test flight in accordance with
manufacturer's specifications and the flight manual
has been accomplished. Aircraft exhibits normal
flight characteristics.

Wayne Miller 1626752
Flight Test

Dates	Pilote	Nombre membres d'équipage	Voyage	Heures Times		Durée du vol	Kilo-mètres parcourus	Nombre de passagers	Nombre d'atterrissages
Date	Pilot	Number of Crew	Journey	Départ	Arrivée	Duration of Flight	Distance Flown Kilo-metres	Number of Passengers	Number of Landings
				Departure	Arrival				
5-21-8	TACA.1222.0	1	Inspect E.C.T on	Report	91.207(1)	1	1	1	1
			Date to 5/00. —	Brought forward	Michael A. Benin 015387019				
CRS#: TH5R223N VIP AVIONICS, INC. BRAINARD AIRPORT HARTFORD, CT 06114 11/11/98 W20GU TB-20 A/C TT: 1253.93 WO# 2175 SOCATA S/N: 655 1AV. FAR 91.411 has been accomplished IAW Part 43 app E para A,B,D. This altimeter has been tested to 20,000 feet and found satisfactory for return to service. Pertinent details are on file at this facility. Make: IFR Model: IFR45-20 Serial #: 011 Automatic pressure altitude reporting system tested to 20,000 feet as required by FAR 91.411 IAW FAR 43, app E. para. C. Make: Narco Model: AR-850 Serial #: 11257 ATC transponder tests and inspections required by FAR 91.413 were performed and found to comply with FAR part 43 app F. Make: King Model: KT-76A Serial #: 47373 <i>David Mark</i> AUTHORIZED SIGNATURE TH5R223N									
A reporter Carried forward.									

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

The FAA Form 8130-3 is required for all aircraft registered in the United States. Other countries such as Canada, Mexico, etc., may have equivalent acceptable documents. IT IS RECOMMENDED THAT OWNERS BE FAMILIAR WITH THE FAA FORM 8130-3.

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

5-7-99
Inst. 1. New Side Standby Vacuum System in accordance with
STC SA7628SW, Revise Aircraft Weights and Balance, Complete oil fill
from 337. Walter J. Moore ACP 1422624

6-3-99. TACH. & TOTAL 1291.8. Opened all Inspection Panels and Inspect cables and Pulleys.
control Surfaces and ATTACH Points, lubricate as required. Replace Vacuum
Pump 211CC SN 73921 Repro Pump. also replaced filter in System. Inspect
E.L.T. as per 91.207(d). Replaced Nose Gear Down Switch PIN. TB2061032005
CLW AD 87-22-02 RE Visited Inspections for cracks. None found at this time.
Due 1391.8. AD 98-08-23 cracks in Main Landing Gear being not due at
this time. Due to rubbing of landing and T.I.S.

I certify that this Aircraft N20644 has been
inspected in accordance with a. ANNUAL
inspection and was determined to be in
airworthy condition

Michael A. Bener

Date 6-3-99 Inspection Authorization
015389017

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterri- sages Number of Landings
				Départ Departure	Arrivée Arrival				
				Report Brought forward .					
CORROSIONTM TREATMENT CENTER <i>Gray Lady Aviation</i> N° 9750 <u>7-20-99</u> TREATMENT DATE <u>N206U</u> AIRCRAFT SN OR N NUMBER I certify that this aircraft has been treated with Corrosion X (Mil-C81309E) to stop and arrest corrosion. Treatment is effective for 18-24 months, based on environmental conditions. Re-treating is recommended when effectiveness fades -- as determined by either time or visual inspection. _____ TECHNICIAN'S SIGNATURE <u>210020784</u> _____ A & P NUMBER									
				A reporter					
				Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture


AEROSPATIALE MATRA

 North Perry Airport 7501 Pembroke Road
 Pembroke Pines, FL 33023 FAA CRS # URZR891L


Date May 19, 2000

Aircraft Type

TB 20

SN 655

Registration N20GU

Meter Time 1375.16

Tach

T. T. 1375.16

W/O No. 1543

Completed Annual inspection IAW FAR part 43 subpart D, aircraft was found to be in an airworthy condition. Replaced right main landing gear door attachment links, resealed left and right fuel tank panels, replaced upper cowling oil access door latch, replaced upper and lower hinges on rudder trim tab. Replaced left and right cabin door balancing rods, replaced engine oil pressure line, replaced engine driven fuel pump cooling hose, replaced flap attachment hardware. Replaced six loose rivets under fuselage, replaced landing gear emergency valve, replaced access doors forward and aft hooks and roll pin for latching mechanism, replaced #5 cylinder aft baffle, replaced ELT battery new expiration date, June 2002, replaced nose wheel assembly, replaced o-rings of left and right fuel caps, replaced CHT probes on #1 and #3 cylinders, replaced attach bracket for tail cone support. Replaced gasket on induction air box. Replaced left and right brake linings. Replaced placards in cargo compartment and main landing gear. Replaced hardware under oil cooler. Replaced protective boot on oil temperature probe. Repaired co-pilot's locking mechanism, repaired upper attachment of balancing rod for co-pilot's door. Removed muffler, repaired by CRS # VUWR0480 under w.o. 0162 dated 5/17/00 and reinstalled. Cleaned and treated corrosion at aircraft I.D. plate and on rudder near trim tab hinge. C/W S.B 10-092 reapplication of corrosion protection C/W AD76-07-12 Bendix ignition switch, no defects noted. Checked AD's through AD2000-08-09, no new applicable. Performed ground run for operational and leak tests. Aircraft systems test normal. See Socata work order # 1543 for details.

 Signature Dean Fantinato Dean Fantinato CRS # URZR891L.

 I certify that this Aircraft/Engine/Propeller/
 Appliance has been inspected/repared in
 accordance with an Annual

 Inspection and determined to be in Airworthy
 condition. Permanent details on file under
 W/O# 1543 and copy given to customer.
A/cft. T.T. 1375.16Engine T.T. 1375.16 Date 5/19/2000

Signature

Dean Fantinato

DEAN FANTINATO

CRS-URZR891L

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

23

Dates
Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol
Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle
Stamp and signature of overhauler
and of controlling Authority

4/9/00 Replaced Pilot's seat belt assembly with
new p/n TB1077013104 see Sorata WO. # 1552
for Details Dean Antone CR5#10728911 L

PDCS. 00000000

ALTIMETER CORRECTION CARD

ALT S/N 011		DATE: 10-20-00		INSP: E Rowley	
TRUE	ERROR	TRUE	ERROR	ALT	FRICTION
-1000	0	14000	-60	1000	30
0	0	16000	-50	2000	40
500	0	18000	-30	3000	40
1000	+5	20000	-20	5000	60
1500	+20	22000		10000	60
2000	0	25000		15000	70
3000	+20	30000		20000	70
4000	+15	35000		25000	
6000	+5	HYSTERESIS		30000	
8000	0			35000	
10000	-30			CASE	
12000	-60	50%	+10	LEAK	18k
		40%	+10		

VIP AERO INSTRUMENTS AND AVIONICS
FAA REPAIR STATION #TH5R223N

10/20/00 WO# 5084
N20GU SOCATA
TB-20 S/N: 655
A/C TT: 1,438.2 HOBBS:

COMPLISHED IAW PART 43 APP E PAR A,B,D.
N TESTED TO 20,000 FEET AND FOUND SATISFACTORY FOR
TINENT DETAILS ARE ON FILE AT THIS FACILITY.

Ed Rowley
MODEL: IFR 45-20 SERIAL #: 011
ITUDE REPORTING SYSTEM TESTED TO 20,000 FEET
411 IAW PAR 43, APP E. PARA. C.

Ed Rowley
MODEL: AR-850 SERIAL #: 11257
ND INSPECTIONS REQUIRED BY PAR 91.413 WERE
COMPLY WITH PAR PART 43 APP F.

Ed Rowley
ODEL: KT76A SERIAL #: 47373
limits specified in PAR 91.171 for IFR operations.

AUTHORIZED SIGNATURE TH5R223N

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Departure Arrivée Arrival	Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Report Brought forward.				
12/4/00			Removed plastic wing tips and installed R.M.D. Aircraft Lighting Inc. Fiber glass wing tips in accordance with FAA approved 337 Form this date. Inspl 2 Herald A + P2040789					
1/20/01			Tach 1478. Replaced all tires & tubes. Retract gear. Inspl 2 Herald A + P2040789					
				A reporter Carried forward.				

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

24

Dates
Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

N 20GU Tach 1500.6 Work Order# 22511

Removed Narco AR-850 s/n 47670. Unit repaired Narco
Avionics 4/26/01, WO# 32741M. Reinstalled tested
I.A.W. Part 43 Paragraph A and C. Satisfactory.

Conrad P. Wondolowski

05/24/01

the radio shop inc. airport worcester, ma 01602
FAA Repair Station TD5R219N

NARCO AVIONICS INC.	
SERVICE TAG	
MODEL #	AR 850
SN	47670
DATE	5/24/01
W.O.#	32741
DETACH AND AFFIX TO LOGBOOK	

SERVICE DE L'AÉRONEF • AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
				Report Brought forward.					
6/1/01	Tach. TITAF 1502		Jacked A/C checked & lubed gear. Replaced nose gear balancing rods. Replaced fuel filter element. Replaced wing spars. Replaced Lard mount on engine. Replaced induction air filter element 91-05-02 inspected fuselage nose gear frame. due again 2002 hrs. Checked TITAF FAR 91-207(C).						
I certify that this Aircraft N206U has been inspected in accordance with the Manual inspection and was determined to be in airworthy condition. <i>Joseph E. Flernard</i> Date <i>6/1/01</i> Inspector's Authorization 2010789									
Durée totale des vols : depuis dernière R.G. : Total flying time since last major overhaul				A reporter Carried forward.					
				depuis fabrication : Since manufacture					

SERVICE DE L'AÉRONEF - AIRCRAFT

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Dates

Date _____

12-LT-01

TRCH 1578.3

Replaced Vacuum Pump 211CL, SN 98269

Joseph E. Howard Atty 12040789

Stamp and or

ification #203-6-1009
AR 145 and with respect to that work the
Certificate Number JAA 4802

NESROGAN

SERVICE DE L'AÉRONEF • AIRCRAFT RECORD

26

Dates

Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority



North Perry Airport 7501 Pembroke Road
Pembroke Pines, FL 33023 / FAA CRS # URZR891L / JAA #5152

Date January 22, 2002

Aircraft Type

TB 20

SN 655

Registration

N 20GU

Meter Time

1595.59

Tach

T. T. 1595.59

W/O No. 1889

1. Replaced static discharger wicks P/N TB2061911001 on rudder and L/H Aileron.
2. Dressed propeller blades.
3. Checked all landing gear tires pressure to Mfg. Specs.

I certify that this Aircraft/Engine/Propeller
Appliance has been inspected/repared in
accordance with an DISCREPANCIES
inspection and determined to be in Airworthy
condition. Permanent details on file under
W/O# 1889 and copy given to customer.

Actl. T.T. 1595.59Engine T.T. 1595.59Prop T.T. 1595.59 Date 1.22.02Signature K. Phongsavath KAM PHONGSAVATH

CRS-URZR891L/JAA-5152

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcours Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
				Report Brought forward .					
			Tach + TTAF 1646. Jacked AK checked & labeled gear serviced battery. Replaced E-27 Bracket & Battery & checked 1 NW KHR 91:207 (C) battery plate 8/04. C/W AD 2001-23-04 inspect Rudder lower hinge. due again 1746 hrs. AD 2001-23-95 NA to mesh seats. C/W SB 10-130 checked avion control & imbls.						
				I certify that this Aircraft N206V has been inspected in accordance with a <u>Manual</u> inspection and was determined to be in airworthy condition. <i>Joseph E. Howard</i>					
				Date		Inspection Authorization			
						2040789			
				A reporter					
				Carried forward.					

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

27

Dates

Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

9-24-02 TACH. 1669.9. Removed and replaced Aircraft. Bottom. with Gill G-35 Bottom.
Walter Moore AXP/422024

THE RADIO SHOP INC. MUNICIPAL
FAA REPAIR STATION

Altimeter and Static Sy

Altimeter Make	Altimeter Model #	Transponder Model #
IFR	45-2	45-2
King	45-2	45-2

At 29.92Hg A/C Alt reads 592

At Field Elevation A/C reads 30.3

Check Points	Test Alt Correct SN 415093	Scale Error	Tol- erance
-1000	1,000	-1010 -10	20
0	0	-15	20
500	500	480 -20	20
1000	1,000	985 -15	20
1500	1,500	1480 -20	25
2000	2,000	1990 -10	30
3000	3,010	2990 -10	30
4000	4,000	3990 -10	35

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

28

Détails vérifications et travaux entretiens — Révisions partielles ou générales
 Modifications — Essais en vol
 Particulars of inspections and maintenance — Minor or major overhauls
 Modifications — Test flights

Cachet — Signature réparateur
 Organisme de contrôle

Stamp and signature of overhauler
 and of controlling Authority

Dates
 Date

3/28/03 REMOVE + REPLACE WALDON AUXILIARY FUEL
 PUMP. INSTALLED WALDON PUMP SOCATA
 # TB20 61015000. SYSTEM CHECKED +
 TESTED. *Joseph E. Howard*
 ATP 2040789

Since manufacture

Total flying time since last major overhaul

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

29

Détails vérifications et travaux entretiens — Révisions partielles ou générales

Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls

Modifications — Test flights

Cachet — Signature réparateur

Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

Tach 1774F 1693 hrs. Jachet A/C checked + lubed gear. Repacked
ball Brake disc 164-19 and all linings. Repacked all wheel
bearings. Checked ELT, 174 FAR 91 207 G. C/A AD 2003-04-03
inspected Citeron gimbal due again 1793 hrs. C/A AD 2001-23-04
inspect Lower Rudder hinge due again 1793 hrs.

I certify that this Aircraft **N206V** has been
inspected in accordance with a **Manual**
inspection and was determined to be in
airworthy condition.

Joseph E. Howard

Date

5/11/03

Inspection Authorization

2040789

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

30

Dates	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol	Cachet — Signature réparateur Organisme de contrôle
Date	Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Stamp and signature of overhauler and of controlling Authority

CRS# D5QR162X
AERODYNAMICS AVIONICS
104B West Apron Drive
Reading, PA 19605

05/22/03 WOH 28308
N20GU AEROSPATIALE
TB 20 S/N: 655
A/C TT: 1,695.7 HOBBS:

1AV. KLN-89B GPS/1063 Removed Northstar M3 Approach GPS System. Installed Bendix/King KLN-89B GPS, Bendix/King KI-208A Indicator, & Ameri-King Corp. AK-950L Switch/Annunciator IAW Bendix/King KLN-89/89B GPS Installation Manual 006-10522-0003 Rev. 3 dated May, 1999, Bendix/King KI-208A/209A Installation Manual 006-10543-0000 Rev. O dated October, 1996, & Ameri-King AK-950L Installation Manual Doc. No. IM-950 dated November 22, 1996. Aircraft Wt. & Balance modified to reflect this change. Reference FAA Form 337.

2AV. P.S.ENG.INTERCOM/CJ-02124 Removed Telex PC4 Intercom. Installed P.S. Engineering PCD 7100 Intercom System IAW P.S. Engineering PCD7100 Installation Document P/N 200-971-0001 Revision 1 dated December, 2000. Aircraft Wt. & Balance modified to reflect this change. This is a minor alteration.

Timothy J. Kiper
CRS# D5QR162X

AERODYNAMICS of Reading, Inc. 104-B West Apron Drive Reading, PA 19605 UJDR862L
LOG ID# 190 20-May-2003 WOH# 8710 AC TT 1695.8
N20GU S/N 655 SOCATA TB-20 Trinidad

Pg 1 / 1


1. TROUBLESHOOT LANDING GEAR IN-TRANSIT LIGHT REMAINS ON WITH LANDING GEAR RETRACTED. JACKED AIRCRAFT. RETRACTED GEAR; FOUND RH MAIN LANDING GEAR UP INDICATION SWITCH WAS NOT FULLY ENGAGED WITH LANDING GEAR RETRACTED AND THAT SWITCH ACTUATING ARM WAS BENT. STRAIGHTENED ACTUATING ARM; ENSURED THAT THERE WAS NO UNDUE STRESS ON SWITCH AND ARM WITH LANDING GEAR RETRACTED. LANDING GEAR RETRACTION OPERATIONAL CHECK WAS SATISFACTORY. REMOVED AIRCRAFT FROM JACKS.

WORK ACCOMPLISHED IN ACCORDANCE WITH S.O.C.A.T.A. TB-20 MAINTENANCE MANUAL.

TL R R
CRS# UJDR862L AUTHORIZED SIGNATURE

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

31

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
9/24/03	N20GU Tach 1734.9 Replaced right main tire with new 15 X 600 X 6 6pr Flight Custom tire. Replaced nose tire with new 500 X 5 6pr Flight Custom tire. Inflated to proper pressure.  David Wunderlich IA185387229 Corporate Flight Concepts	

[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

32

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
6/18/04	Removed Anjou Aeronautique safety lap belts (3) type 343-1 and replaced with Anjou-Aero safety lap belts 3491127-12 identified by Socata part number Z00.N6003987223 as required by FAA AD 2003-26-06 in service bulletin SL10-057.	James K. Hayer Pilot Certificate # 2764655
9/15/04	Replaced Spring & Lock on Landing Gear Switch on Left Hand Side. Swung Gear and Lubed Complete System. Ops Normal Returned to Service.	<i>[Signature]</i> AsP261764891

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Departure	Arrivée Arrival	Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
---------------	-----------------	--	-------------------	--	--------------------	--	--	---	--

Altitude Certification, Inc. CRS ZY7R894X

1386 Auburn Ct., Boynton Beach, FL 33436 Phone: (561) 596-6359

Maintenance Release and Return to Service Form ACI-007

Manufacturer Aerospatiale Model Number TB20 Total Time 1810.14
 Registration N20GU Serial Number 655 Total Landings unk

PILOTS

COPILOTS

STANDBY

Altimeter

Transponder

Encoder/ADC

P/N	S/N	P/N	S/N	P/N	S/N
unk	unk				
066-1062-00	47373			n/a	n/a
unk	unk			n/a	n/a

On the date of 10/6/2004 the altimeter(s) was tested to 20,000 feet.

On the date of 10/6/2004 data correspondence was tested to 20,000 feet.

On the date of 10/6/2004 the static system(s) was leak tested and inspected.

On the date of 10/6/2004 the transponder(s) was tested.

I certify that the altimeter and static system tests required by 14 CFR § 91.411 and transponder tests, including data correspondence, required by § 91.413, have been performed and found to comply with 14 CFR part 43, appendix E and F.

Pertinent details of these tests and inspections are on file at this repair station under Work-Order Number 0011

Signature

John R. Lys

Date

10/6/2004

Certificate #

CRS ZY7R894X

A reporter
Carried forward.

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

33

[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Depart- ture	Arrivée Arrival				
				Report					
				Brought forward .					
BOCA AVIATION 3700 Airport rd. Boca Raton, Florida, 33431 N20GU AIRFRAME LOGBOOK ENTRY November 18, 2004 SOCATA TB20 S/N 655 TACH: 1812.55 1. REMOVED THE RH BRAKE ASSY REPLACED O RINGS AND REINSTALLED BRAKE ASSY IAW THE MFG M/M CHAPTER 32, OPS AND LEAK CHECK OK. THE AIRCRAFT & COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE CONCERNING THE WORK PERFORMED. PERTINENT DETAILS ARE ON FILE AT THIS AGENCY UNDER WORK ORDER #.MP-218 DEWAYNE THAMES CRS #LCPR025G <i>Dewayne Thames</i>									
BOCA AVIATION 3700 Airport rd. Boca Raton, Florida, 33431 N20GU AIRFRAME LOG ENTRY SOCATA TB20 S/N 655 TACH: 1832.92 November 26, 2004 1. REPAIRED LEAKING F/F GAUGE BY SECURING THE FUEL LINE @ THE GAUGE LEAK CHECK OK THE AIRCRAFT & COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE CONCERNING THE WORK PERFORMED. PERTINENT DETAILS ARE ON FILE AT THIS AGENCY UNDER WORK ORDER #.MP-233 DEWAYNE THAMES CRS #LCPR025G <i>Dewayne Thames</i>									
				A reporter					
				Carried forward.					
Durée totale des vols : depuis dernière R.G. : Total flying time since last major overhaul				depuis fabrication : Since manufacture					

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

34

Dates

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Cachet — Signature réparateur
Organisme de contrôle

Date

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Stamp and signature of overhauler

AIRFRAME LOG

N20GU DATE:7-1-05 TACH: 1839.85

- *Lubed cables and pulleys
- *Swung Landing Gear system normal
- *C/W FAR Part 91.207(d) ELT
- *C/W AD76-07-12 Ign. Switch function ck.
- *C/W AD2001-23-04 by inspection
- *C/W AD23-04-03 by inspection
- *Replaced Main Battery RG35

The Maintenance above was performed in
Accordance with applicable airworthiness standards. Annual
Inspection completed IAW

FAR Part 43, Appendix D. This Aircraft has
been found to be Airworthy and returned to service.

John C. Clegg
1A261764891

AIRFRAME LOG

N20GU DATE:12-1-06 TACH: 1853.74

- *Lubed cables and pulleys
- *Swung Landing Gear system normal
- *Replaced ELT Battery Next Due 2/09
- *C/W FAR Part 91.207(d) ELT
- *C/W AD76-07-12 Ign. Switch function ck.
- *C/W AD2001-23-04 by inspection
- *C/W AD93-02-05 by inspection
- *Repaired Gable to Main Battery

The Maintenance above was performed in
Accordance with applicable airworthiness standards.
Annual/100 Inspection completed

IAW FAR Part 43, Appendix D. This Aircraft
has been found to be Airworthy and returned
to service.

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
				Report Brought forward.					
LOGBOOK ENTRY: <u>Socata TB020 N206U Tach 1853.74</u> THE STATIC PRESSURE SYSTEM, TRANSPONDER WITH ALTITUDE REPORTING WAS IDENTIFIED TESTED AND INSPECTED I/A/W FAR43 APPENDIX E, PAR A & C, APPENDIX F (FAR91.413) AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THIS TEST IS ON FILE AT THIS REPAIR STATION UNDER W.O. <u>7747</u> DATE <u>Jan 4, 2007</u> SIGNATURE <u>Mark B. Alencida</u> INSP. <u>(MBA)</u> TROPIC RADIO INC. 2695 N.W. 56th ST. HANGER 53-D FT. LAUDERDALE FL. 33309 FAA APPROVED REPAIR STATION # RZ4R510M FT. LAUDERDALE EXECUTIVE AIRPORT* ARCHER RAMP* TELEPHONE # 954-776-4030 <u>KT76A S/N 47373</u>									
CERTIFICATION EXPIRES ON <u>Jan 31, 2009</u>									
				A reporter					
				Carried forward.					
Durée totale des vols : depuis dernière R.G. : depuis fabrication : Total flying time since last major overhaul Since manufacture									

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates	Pilote	Nombre membres d'équipage	Voyage	Heures Times		Durée du vol	Kilo-mètres parcourus	Nombre de passagers	Nombre d'atterrissages
Date	Pilot	Number of Crew	Journey	Départ Departure	Arrivée Arrival	Duration of Flight	Distance Flown Kilo-metres	Number of Passengers	Number of Landings



North Perry Airport 7501 S. Airport Road, Pembroke Pines, FL 33023 / FAA CRS # URZR891L / EASA.145.5152

Date September 18, 2007

Aircraft Type

TB 20

SN 655

Registration N 20GU

Meter Time 1859.69

Tach

T. T. 1859.69

W/O No. 3457

1. Replaced L/H cabin door window with new P/N TB1025030108.
2. Replaced nose wheel bearing cups P/N 214-00300, bearing cone P/N 214-00400 and grease felts P/N Z00N7061731100 with new.
3. Cleaned corroded area and repaired the upper surface of the L/H lower spar per DER Approved FAA Form 8110-3 No. EO 07-1533-01-01, dated 23-Aug-07, see FAA Form 337 date 9/17/2007.
4. Replaced L/H main gear door hinge P/N TB2048006125, knuckle P/N TB2048006108, hinge pin P/N TB2048006130, support tab P/N TB2048006131 with new.
5. Secured loose wire bundle at R/H flight control yoke sliding tube.
6. Replace L/H main landing gear up-lock micro switch with new P/N TB2061020002 and Ops. checked good.
7. Removed KS-177 Pitch servo P/N 065-0050-12 S/N 2036 and sent to Banyan Avionics CRS # SD4R514M for inspection and test as per requested by aircraft owner, received servo and re-installed after inspected under W.O. 72715, performed ground operational check normal.
8. Removed KS-179 Pitch trim servo P/N 065-0052-13 S/N 2344 and sent to Banyan Avionics CRS # SD4R514M for inspection and test as per requested by aircraft owner, received servo and re-installed after inspected under W.O. 72734, performed ground operational check normal.

I certify that this aircraft has been inspected in accordance with a pre-buy inspection using Socata TB 20 Maintenance manual Chapter 05-20-06, a list of discrepancies and unairworthy items date 6/29/2007 has been provided for the aircraft owner/operator.

The aircraft Airframe, Engine, Propeller, Appliance Identified Above Was Repaired And Inspected In Accordance With Current Regulation Of Federal Aviation Administration And Is Approved For Return To Service For the Work Performed. Permanent Records Of The Repair Are On File At This Repair Station Under W.O. # 3457, Date: 9-18-07 Signature: *K. Phongsavath* CRS # URZR891L / EASA.145.5152 KAM PHONGSAVATH

Total flying time since last major overhaul

Since manufacture

KAM PHONGSAVATH

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

37

Dates

Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

10/24/07 ACTT-1859.69 Inspected aircraft for
Ferry flight from KTHW to KLNA for the
purpose of maintenance. Aircraft was found to
be in an airworthy condition for ferry flight.
Good for one flight only. ~~Signature~~ CRS# 21228916

Aircraft N20GU was striped and painted.
Dupont Clear Coat 3.4 HG-C
Awlgrip:8003 Matterhorn White
Dupont: Las Vegas 10494
Ming Blue 10714
Florida Aero Paint, Inc.
(561) 642-7820 Date:02/01/08
Flight controls removed, checked for balance
and installed by: De Mohr
A&P# 137508586

[illegible]

Durée totale des vols : depuis dernière R.G. : _____ depuis fabrication : _____
Total flying time since last major overhaul _____ Since manufacture _____

38

Dates	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol	Cachet — Signature/réparateur Organisme de contrôle
Date	Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Stamp and signature of overhauler and of controlling Authority


N20GU		DATE: 03-01-09
AIRCRAFT S/N: 655		
TACH: 1865.2	TOTAL TIME: 1865.2	
ENG TT: 1865.2	ENG TSMOH: <i>Q/A</i>	
PROP TT: 1865.2	PROP TSMOH: 641.9	

Complied with **Airframe Annual Inspection**

Description of Work Performed: Serviced tires and battery.
Lubed wheel bearings and control surfaces.
Replaced in-line and regulator vacuum filters. Replaced
SCAT tubing on cabin heat ducting at firewall.
Removed and Replaced ELT battery, new date **MAY 2011**
Complied with ELT 91.207 inspection.

Airworthiness Directives:
AD 2007-02-04 C/W visual inspection, no defects noted
AD 2003-04-03 C/W visual inspection, no defects noted
AD 2001-23-04 C/W visual inspection, no defects noted

This Airframe has been inspected in accordance with an
Annual inspection and found to be in Airworthy Condition.



Michael H. Hutz A&P 570558740 IA

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates
Date

TROPIC RADIO INC.

2695 N. W. 56TH ST. HANGER 53-A
FT. LAUDERDALE, FL 33309FAA APPROVED REPAIR STATION #RZ4R510M
FT. LAUDERDALE EXECUTIVE AIRPORT *ARCHER RAMP*

PHONE: 954-776-4030



SERVICEABLE

Kilo-
mètres
parcours
Distance
Flown
Kilo-
mètresNombre
de
passagers
Number
of
PassengersNom
d'atter
sage
Num
of
LandiMake and Model ALTIMETER - PressurePart No: 1ER45-20 Serial No: 0011Customer: Palm Beach A/CInspected By: (ms) Date: Sept 17, 09

The component identified above was inspected and functional tested in accordance with current Federal Aviation Regulations and was found Airworthy for Return to Service.

Altimeter Calibrated to 20,000 Ft. I.A.W. FAR PART 43, APP E, (b) (FAR 91.411)Pertinent details of this inspection are on file at this Agency under Work Order # 9351Authorized Representative Mark B. AllenDate Sept 17, 2009SIGNATURE Mark B. Allen

TROPIC RADIO INC. 2695 N.W. 56th ST. HANGER 53-A

FT. LAUDERDALE FL 33309 FAA APPROVED REPAIR STATION # RZ4R510M

FT. LAUDERDALE EXECUTIVE AIRPORT *ARCHER RAMP*

TELEPHONE # 954-776-4030 WWW.TROPICRADIO.COM

KT76A S/N 47373

AR050 S/N 47670

CERTIFICATION EXPIRES ON Sept. 30, 2011A reporter
Carried forward.Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhauldepuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

39

Dates

Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en volParticulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flightsCachet — Signature réparateur
Organisme de contrôleStamp and signature of overhauler
and of controlling AuthoritySupplemental Log Book Entry
Annual Airframe

Reg: N20GU

Date: 10/01/09


Model: TB20

Tach: 1866.3

S/N: 655

ACTT: 1866.3

Performed **Annual Inspection** in accordance with FAR Part 43, appendix "D". Complied with all applicable AD's thru 2009-19. **AD91-05-02**, P/C/W by Inspection of Fuselage Frame for Cracks, **Next Due @ 2000.0**. **AD98-18-13**, Main Landing Gear Attach Bracket, **Next Due at 4000.0 Hours ACTT**. C/W **AD01-23-04** by Inspection of Rudder Lower Hinge Fitting, **Next Due @ 09/2010**. C/W **AD03-04-03** by Inspection of Aileron Control Gimbal Joints IAW SB#10-130, **Next Due 1966.3**. C/W **AD76-07-12** by Inspection and Operation of Ignition Switch, **Next Due @ 1966.3**. Performed Pitot/Static/Transponder Test IAW FAR 91.411 and 91.413 by Tropic Radio Inc., WO#9351. Next due September 2011. Performed Annual ELT IAW FAR 91.207 (d). ELT Transmitter Battery expiration May 2011. Remove Right Main Landing Gear to assist and gain access for "Field Repair" of Right Wing Lower Spar Cap. Repaired upper surface of R/H Lower Wing Spar in accordance with DER Approved FAA Form 8110-3. Aviation Engineering Consultants EO 09-1556-01-01, rev. Dated 16-Sept-2009. See FAA Form 337 dated 09/24/09. Install Right Main Landing Gear, Prime Wing. Corrosion removed and Left Wing Rear Spar Attach Bracket Fittings treated with Zinc Chromate. Remove and replace Left and Right Wing Flap Bellcrank Brackets with new P/N#TB2027005111 and P/N#TB2027005112. Installed Overhaul Exhaust System by Aerospace Welding as follows: Muffler P/N#TB20.56010001-R, WO#128981; L/H Manifold Cylinder #4 P/N#TB20.56000008-R, WO#128982; L/H Pipe Cylinder #6, P/N#TB20.56000006-R, WO#128983; Stub Riser P/N#TB20.56000011-R, WO#128984; R/H Manifold Cylinder #3, P/N#56000009-R, WO#128985; Stub Riser P/N#TB20.56000011-R, WO#128986, R/H Pipe #5, WO#129183. Replaced (8) Exhaust Clamps with new P/N#TB1056008001. Remove and replace R/H Stabilator Bearing Block Assy with new P/N#TB2034021004. Remove and reinstalled Aft Rudder Push-Pull Control Rod IAW Socata TB20 M.M. Remove and replace L/H and R/H Squat Switch Brackets with new P/N#TB204149100 and P/N#TB2041410149. Remove and replace Left Main Landing Gear Microswitch with new P/N#TB3061018003. Remove and replace Pilot and Co-pilot door extenders with new Cabin Door Extenders P/N#ZOO7070780005. Remove and replace Nose Gear Emergency Extension Cylinders with new Nose Gear Emergency Compensating Cylinders P/N#ZOON7077631301. Strobe Tube Connectors cleaned connectors and reinstalled. Remove and replace Brackett Induction Air Filter with new P/N#BA-7112. Remove and replace Windshield Visor Clips with new P/N#ZOO7788014136. Remove and replace Left and Right Aileron Static Wicks, Left and Right Flap Static Wicks, Left and Right Stabilator Wicks and Rudder Static Wick with new P/N#TB2061911001. Fabricate, paint and install Right Wheel Cover. Remove and replace Nose Wheel Bearings with new P/N#08125 and P/N#08231. Removed Left Brake Caliper, cleaned rust from pins and bushings, lubed and reinstalled. Bled Right Brake. Remove and replace Central Vacuum Filter with new P/N#AAD9-18-1. Corrosion X applied to aircraft. I certify that this Aircraft has been inspected/repared in accordance with an **Annual Inspection** and has been determined to be in an airworthy condition and that work described above was accomplished and inspected in accordance with current FAA regulations and is approved for return to service. -END-


 Steven J. Van Antwerp 261511091

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

40

Dates

Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en vol

Particulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flights

Cachet — Signature réparateur
Organisme de contrôle

Stamp and signature of overhauler
and of controlling Authority

April 28 2010 Tach 1914.38 AFTT 1914.38

repaired left gear down light common plug at gear well lubricate down locks both sides m/g remove and replace both m/g tires and tubes replace both m/g Axel lock washers replace all brake pads install new outer grease seal on left wheel grease both m/g wheel bearings refill hydraulic fluid reservoir perform landing gear operational check good at this time

(C. M. D. L. A. T. 1936494405

Removed and dyed all Interior plastics around windows and overhead with SEAL warm grey. Recovered all seats with eclipse pearl Grey and prou Rumba Fabric, cut + Bound new carpet and installed in Aircraft, Dyed baggage compartment cover. All certifications were supplied with this logbook entry.

TT 1866.59 A+p 591368495

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

41

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
5-4-10	INSTALL NEW RH TIP PLAXY COVER @ WING TIP. old one CRACKED MARK MCALPHE PILOT	1915-26 HNS ✓

**** FAA / PMA APPROVED PART ****

ITEM: WING TIP LIGHT LENS-RH (CLEAR)

PART NUMBER: **W-2403-RH**

AIRCRAFT MAKE AND MODEL: SOCATA TB 9, TB 10, TB 20, TB 21, TB 200

SERIAL NUMBERS: ALL SNS

MANUFACTURE DATE: 03-29-2010 MANUFACTURE CODE: 1155581

FOR CONTINUED AIRWORTHINESS SEE AIRCRAFT P.O.H. OR SERVICE MANUAL

APPROVED

915 Kearsley Park Blvd
Flint, MI 48503
(810)-235-1402
www.glapinc.com
Great Lakes Aero Products, Inc.

PLEASE KEEP THIS TAG FOR YOUR LOG BOOK.

des vols : depuis dernière R.G. : depuis fabrication :
time since last major overhaul Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

42

Dates	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol	Cachet — Signature réparateur Organisme de contrôle
Date	Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Stamp and signature of overhauler and of controlling Authority

Above and Beyond Aviation
Novato, CA. 94903

351 Airport Road
Ph: (415)897-9549 fax: (415)8979569

Date: 12/1/2010
Make: SOCATA TB-20

N20GU

Tach: 1957.47
Total: 1957.47

Aircraft opened, serviced and inspected in accordance with a checklist conforming to FAR 43, Appendix D for Annual Inspection. Aircraft lubricated per SOCATA lube chart. Repacked all wheel bearings. Replaced nose wheel bearings and races. Serviced and installed new G-35 aircraft battery. Tested ELT I/A/W FAR 91.207(d). Replaced vacuum system filters. Checked fuel system filters. Complied with AD 2001-23-04, lower rudder hinge inspection, accomplished by compliance with SB10-114-55. Complied with AD2003-04-03, aileron gimbal inspection, accomplished by compliance with SB10-130-27. Replaced right and left brake discs. Replaced right and left brake linings. Resealed right and left main gear actuators. Resealed nose gear actuator. Resealed nose gear strut and serviced to proper pressure. Replaced all landing gear up stop bumpers. Repaired left main gear wheel well with fiberglass repair. Replaced left main gear upper door hinge half. Serviced hydraulic system and performed gear swing. Resealed pilots' left brake master cylinder. Replaced pilots right master cylinder. Bleed brake system. Replaced left and right aileron inner and outer hinge bearings. Replaced lower rudder hinge bearing. Replaced left stabilator hinge bearing assembly. Adjusted stabilator trim cable tension. Replaced smoking rivets in right wing trailing edge. Replaced rivets in left upper tail cone attachment bracket. Replaced right and left fuel cap o-rings. Resealed left fuel tank inboard access panel. Replaced multiple wing access panel attachment screws. Replaced cabin dome light assembly and lamp. Replaced pilots map light assembly and lamp. Replaced alternator and parking brake enunciator light lamps. Replaced multiple overhead console screws. Replaced right cabin door window. Repaired lower cowl at tail pipe protrusion due to rubbing with tail pipe. Ops check good.

I certify that this Aircraft has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

Signature



A&P 572578187 I.A.

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

43

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
	July 20 2011 TACH 2049.0 Replace both M/G tires with new MICHELIN 15X600-6 6PLY Tires cube gear as required	 11/30/11/11
10-15-2011	OCT 15 2011 TACH 2098.14 UPDATE GPS DATABASE - KING GPS. UPDATE GPS DATABASE - CURRENT "MOVING MAP DISPLAY" REPAIR ELECTRICAL FAILURE TO INTERCOM IN STALL <u>IPAD</u> JACK FOR MUSIC ON INTERCOM Frank Ruiz Avionics Fresno CA Note by owner → 	

Dat
Da

1/3/2012

N20GU

TACH:2101.4

WOM6420

BARBER AVIATION

4130 AVIATION DRIVE

MADERA CA,93637

(559)675-0183

SOCATA TB-20

SN: 655

ACTT: 2101.4

AIRCRAFT INSPECTED THIS DATE. REPLACED 1EA AAD9-18-1 PNEUMATIC FILTER, 1EA B3-5-1 PNEUMATIC FILTER, REPLACED LEFT AND RIGHT FUEL CAP O-RINGS WITH NEW. REPLACED NOSE WHEEL BEARINGS AND RACES WITH NEW 08231 RACE AND LM67048 BEARING. REPLACED 1EA TAIL NAV BULB WITH NEW Z00-N7445771403 TAIL NAV BULB OPS CHECK GOOD. COMPLIED WITH AD2003-04-03 AILERON GIMBAL INSPECTION BY VISUAL INSPECTION IAW SB 10-130 27 NO DEFECTS NOTED NID AT ACTT: 2201.4. COMPLIED WITH AD2001-23-04 RUDDER HINGE INSPECTION BY VISUAL INSPECTION NO DEFECTS NOTED NID ACTT:2201.4. COMPLIED WITH AD91-05-02 FUSELAGE CRACKING BY VISUAL INSPECTION IAW SB No. 42/1 NO DEFECTS NOTED NID AT ACTT: 2601.4 ELT BATTERY REPLACED WITH NEW B52166 AND ELT TESTED IAW 91.207(D) BATTERY EXP 1/2014. REPLACED LEFT AND RIGHT BRAKE LININGS WITH 8EA 066-10600. I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER 43.13(D) AND WAS DETERMINED AIRWORTHY AT THIS TIME.

RON DIAZ 565543431A

TRANSIERRA
TECHNOLOGY

N20GU

Tach reads: 2101.55

Performed biannual pitot static and transponder /encoder check per FARs
91.411, 91.413 and FAR 43 Appendix E and F. System certified to 20,000'.

Aircraft system meets all FAA requirements.

Results on file CRS DD3R445L.

END

Details of work accomplished are on file at this agency under W/O 15068

Authorized Signature

Date

1/06/2012

FAA REPAIR STATION # DD3R445L 4130A AVIATION DR MADERA, CA 93637 (559) 675-8320


Dur
Toti

A reporter
Carried forward.

44

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
	MAKE Socata MODEL TB-20 S/N 655 REG NO N20GU WORK ORDER 1015-08-2012 Barber Aviation 4130 Aviation Drive Madera, ca 93637 Phone: 559-675-0183 DATE 8/17/2012 A/C TSN 2162 41 TACH 2162 4 Airframe Entries (1) Found defective tach cable replaced with new 57004100 Tach cable assy. Ground ran aircraft no defects noted.... (3) Removed and replaced battery with new Gill G-35 SN: G02730970. Maintenance Release The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1015-08-2012, Dated 8/17/2012. DATE: 8/17/2012 SIGNED:  Chris Sharp, A&P 2755348AP Work Order: 1015-08-2012 Printed by EBis 3 (datcomedia.com)	

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Departure		Arrivée Arrival	Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atter- rissage Number of Landings
				Report						
										
N20GU										
Tach reads: 2177.45 Removed Attitude Indicator KG 258 P/N 060-0020-22 S/N 10846 for overhaul. Reinstalled KG 258 P/N 060-0020-22 S/N 10846 post overhaul and function tested. Unit operates normally. ***END***										
Details of work accomplished are on file at this agency under W/O <u>15021</u>										
Authorized Signature  Date 09/17/2012										
FAA REPAIR STATION # DD3R445L 4130A AVIATION DR MADERA, CA 93637 (559) 675-8320										
A reporter Carried forward.										
Durée totale des vols : depuis dernière R.G. : depuis fabrication : Total flying time since last major overhaul : Since manufacture :										

MAKE Socata
MODEL TB-20
S/N 655
REG NO N20GU
WORK ORDER:
1051-10-2012

Barber Aviation

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 11/1/2012
A/C TSN: 2188 48
TACH: 2188 47

45

Airframe Entries

(2) Lubed landing gear.... (3) Found oil pressure terminals loose, tightened all connections ops check good.... (4) Complied with AD2001-23-04, inspected rudder hinges by visual inspection. NID ACTT: 2288 48.... (5) Complied with AD2003-04-03 aileron gimbal joints by visual inspection IAW SB10-13027, no defects noted. NID ACTT: 2288 48

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1051-10-2012, Dated 11/1/2012

DATE: 11/1/2012

SIGNED:



Chris Sharp, A&P: 2755348AP

Work Order: 1051-10-2012

Printed by EBis 3 (datcomedia.com)

MAKE Socata
MODEL TB-20
S/N 655
REG NO N20GU
WORK ORDER:
1076-01-2013

Barber Aviation

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 5/20/2013
A/C TSN: 2217 75
TACH: 2217 74

Airframe Entries

(1) Complied with annual inspection per FAR43(app d). Replaced induction air filter with new BA7112.... (4) Complied with ELT inspection per FAR91.207(d), no defects noted. Battery Expiration Jan 2014.... (5) Removed and replaced pneumatic filters with new.... (6) Complied with AD2001-23-04 Rudder hinge cracks by visual inspection, no defects noted. NID 12mo.... (7) Complied with AD2003-04-03 Aileron gimbal joints by visual inspection IAW SB10-130-27, no defects noted. NID ACTT: 2317 75.... (9) Removed cabin light and cleaned contacts, ops check good.... (10) Reattached left wing root seal with 1300L.... (12) Adjusted stall warning switch to engage with out force.... (13) Removed and replaced nose wheel bearings and races with new.... (14) Removed and replaced brake linings with new.... (16) Replaced pulled rivets with new IAW AC43.13-1B.... (17) Removed and replaced engine after overhaul by Exodus Air. Engine mounts replaced with new.... (18) Complied with AD91-05-02 Fuselage frame cracks by installation of repair kit OPT10915200. AD no longer applies.... (19) Removed forward upper fuselage inspection plates, prepped and repainted.... (20) Stripped and cleaned engine baffling, primed, painted, and installed new rubber seals.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1076-01-2013, Dated 5/20/2013

DATE: 5/20/2013

SIGNED:




Chris Sharp, IA: 2755348AP

Work Order: 1076-01-2013

Printed by EBis 3 (datcomedia.com)

Cachet — Signature réparateur
Organisme de contrôle

amp and signature of overhauler
and of controlling Authority



OIL CHANGED
FILTER CHANGED
[Signature]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

46

Dates	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol	Cachet — Signature réparateur Organisme de contrôle
Date	Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Stamp and signature of overhauler and of controlling Authority

MAKE: Socata
 MODEL: TB-20
 S/N: 655
 REG NO: N20GU
 WORK ORDER:
 1132-08-2013

Barber Aviation

4130 Aviation Drive
 Madera, ca 93637
 Phone: 559-675-0183

DATE: 8/15/2013
 A/C TSN: 2250.71
 TACH: 2250.7

Airframe Entries

(2) Removed and replaced left and right main tires with new Condor 15/8 00x6 Tires and balanced... (3) Removed and replaced #6 EGT probe with new.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1132-08-2013, Dated 8/15/2013.

DATE: 8/15/2013

SIGNED:



Work Order: 1132-08-2013

Chris Sharp, A&P: 2755348AP

Printed by EBis 3 (datcomedia.com)

MAKE: Socata
 MODEL: TB-20
 S/N: 655
 REG NO: N20GU
 WORK ORDER:
 1207-04-2014

Barber Aviation

4130 Aviation Drive
 Madera, ca 93637
 Phone: 559-675-0183

DATE: 4/14/2014
 A/C TSN: 2304.69
 TACH: 2304.68

Airframe Entries

(1) Removed left and right wheel assemblies replaced left and right brake discs with new 164-01900. Removed left and right brake calipers, disassembled, cleaned and inspected left and right calipers. Calipers resealed with new o-rings. Reinstalled calipers and bled left and right brake system. Removed and replaced all brake linings with new.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1207-04-2014, Dated 4/14/2014.

DATE: 4/14/2014

SIGNED:



Work Order: 1207-04-2014

Chris Sharp, A&P: 2755348AP

Printed by EBis 3 (datcomedia.com)

TRANSIERRA TECHNOLOGY

RD

N20GU

Tach reads: 2317.04


Performed biannual pitot static and transponder /encoder check per FARs 91.411, 91.413 and FAR 43 Appendix E and F. System certified to 20,000'.

Aircraft system meets all FAA requirements.

Results on file CRS DD3R445L.

END

Details of work accomplished are on file at this agency under W/O 15285

Authorized Signature 

Date 06/04/2014

FAA REPAIR STATION # DD3R445L 4130A AVIATION DR MADERA, CA 93637 (559) 675-8320

MAKE Socata
MODEL TB-20
S/N 655
REG NO N20GU
WORK ORDER
1222-05-2014

Barber Aviation

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE 6/4/2014
A/C TSN: 2317 05
TACH: 2317 04


Airframe Entries

(1) Complied with annual inspection per FAR43(app d). Removed and replaced induction air filter with new BA7112.... (5) Complied with ELT inspection FAR91.207(d). ELT battery expires: July 2016.... (6) Removed and replaced pneumatic filters with new.... (9) Complied with AD2001-23-04 Rudder hinge cracks by visual inspection, no defects noted. NID ACTT: 2417 05 or 12mo.... (10) Complied with AD2003-04-03 Aileron gimbal joints by visual inspection, no defects noted. NID ACTT: 2417 05 or 12mo.... (13) Removed and replaced left and right door hold open rods with new.... (14) Removed and replaced 40amp buss breaker with new, ops check good.... (16) Removed center headliner, found rivets broken. Removed rivets and installed new. Reinstalled headliner.... (17) Removed and replaced master switch with new, ops check good.... (20) Removed and replaced tail nav lamp with new.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1222-05-2014. Dated 6/4/2014.

DATE: 6/4/2014

SIGNED 

Chris Sharp, IA. 2755348AP

Work Order: 1222-05-2014

Printed by EBis 3 (datcomedia.com)

Carried forward.

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times Départ Departure		Arrivée Arrival	Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Report						
				Brought forward .						
PROP MODEL HC-C3YR-1RF/F7693F PROP S/N PA582B REG NO N20GU WORK ORDER 1375-06-2015				Barber Aviation 4130 Aviation Drive Madera, ca 93637 Phone 559-675-0183		DATE 8/3/2015 A/C TSN 2440 07 PROP TT 222 32 TSPOM 222 32 TACH 2440 06				
Prop Entries (3) Complied with 100hr inspection per FAR43(app d) Dressed propeller blades										
Maintenance Release The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1375-06-2015, Dated 8/3/2015										
DATE: 8/3/2015			SIGNED  Chris Sharp, A&P 2755348AP			Work Order: 1375-06-2015 Printed by EBis 3 (datcomedia.com)				
A reporter Carried forward.										

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul

depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

48

Dates

Date

Détails vérifications et travaux entretiens — Révisions partielles ou générales
Modifications — Essais en volParticulars of inspections and maintenance — Minor or major overhauls
Modifications — Test flightsCachet — Signature réparateur
Organisme de contrôleStamp and signature of overhauler
and of controlling Authority

REPLACE (L) wingtip lens 3-9-2016

** FAA/PMA APPROVED PART - PQ2056CE **

ITEM: WINGTIP LIGHT LENS-LH (CLEAR)

PART NUMBER: W-2403-LH

AIRCRAFT MAKE AND MODEL: SOCATO TB 9, TB 10, TB 20, TB 21, TB 200

SERIAL NUMBERS: 275 & UP

APPROVED

REPL PN: TB20 10001102

MANUFACTURE DATE: 02-29-2016 MANUFACTURE CODE: 1216230

FOR CONTINUED AIRWORTHINESS SEE AIRCRAFT P.O.H. OR SERVICE MANUAL

PLEASE KEEP THIS TAG FOR YOUR LOG BOOK.

HAS

2490.79

915 Kearsley Park Blvd
Flint, MI 48503

(810)-235-1402

www.glepine.com

Whife
PILOTGreat Lakes Aero
Products, Inc.

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD


[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

49

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
	MAKE: Socata MODEL: TB-20 S/N: 655 REG. NO: N20GU WORK ORDER: 1529-08-2016 Barber Aviation 4130 Aviation Drive Madera, ca 93637 Phone: 559-675-0183 DATE: 9/8/2016 A/C TSN: 2555 36 TACH: 2555 35 Airframe Entries (1) Complied with annual inspection per FAR43(app d). Induction air filter replaced with new BA7112... (5) Complied with ELT inspection per FAR 91.207(d). No defects noted at this time, function check good. Battery good until Aug 2016. (6) Removed ELT and installed new Ack E-04 elt SN: 016781 in same location as previous installation. Installed remote switch in panel... (7) Replaced both rubber shock mounts in back of pilots cockpit panel. checks good for security... (8) Updated GTN 750 to latest software version 6.11 checks good for update... (9) Removed previous Jaeger clock due to its brightness making it difficult to view. replaced previous clock with new MD 93 Digital clock with usb power ports. checks good for security and operation... (10) Removed KG107 Directional Gyro and replaced with overhauled from PSI SN: 2669, ops check good... (11) Removed and replaced pneumatic filters with new... (12) Removed and replaced L/S and R/S brake linings with new... (13) Cylinder #6 CHT probe had a broken terminal, replaced terminal with new... (14) Complied with AD 2003-04-03 Aileron gimbal joints IAW Socata SB 10-130 27, no defects noted. NID ACTT: 2655.36... (15) Complied with AD 2001-23-04 Rudder hinge cracks IAW Socata SB 10-114 55, no defects noted. NID 12mo... (16) Complied with AD 2011-26-04 Fuel Injector lines by visual inspection, no defects noted. NID ACTT: 2655.36 or next maintenance... (17) Removed, replaced, and balanced main gear tires with new Goodyear 156E66-B1 tires... (18) Removed and replaced nose wheel bearings and races with new... (19) Had complied with by Transierra Technology... (20) Had complied with by Transierra Technology... (21) Complied with AD 2015-24-03 Horizontal Spar corrosion by visual inspection, no defects noted. NID ACTT: 3055.36 or 72mo Maintenance Release The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1529-08-2016, Dated 9/8/2016. DATE: 9/8/2016 SIGNED:  Chris Tharp, IA: 2755348AP Work Order: 1529-08-2016 Printed by EBis 3 (datcomedia.com)	

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Depart- ure	Arrivée Arrival				
				Report					
				Brought forward .					
MAKE: Socata MODEL: TB-20 SN: 655 REG NO: N20GU WORK ORDER: 1687-09-2017		Barber Aviation 4130 Aviation Drive Madera, ca 93637 Phone: 559-675-0183		DATE: 10/1/2017 A/C TSN: 2640 43 TACH: 2640 42					
Airframe Entries (1) Complied with annual inspection per FAR43(app d). Replaced induction air filter with new BA7112... (5) Complied ELT inspection FAR91.207(d). ELT battery expires August 2021... (6) Removed and replaced pneumatic filters with new... (7) Panel lights checked 3 bulbs replaced, one post light for gyro suction gauge replaced, ops check on lights good... (8) Removed and replaced aircraft battery with new... (9) Removed and replaced R/S NAV light bulb with new, ops check good... (10) U/S main gear weight on wheel switch cannon plug repaired... (11) Removed and replaced fuel cap o-rings with new... (16) Removed, replaced, and balanced tires with new... (17) Removed and replaced L/S and R/S brake linings with new... (18) Complied with AD 2001-23-04 Rudder hinge cracks by visual inspection, no defects noted NID 10/2018... (19) Complied with AD2003-04-03 Aileron Gimbal Joint inspection by visual inspection, no defects noted, NID ACTT: 2740 43... (20) Complied with AD2011-26-04 Fuel injector lines by visual inspection, no defects noted, NID ACTT: 2740 43... (21) Complied with AD2015-24-03 Horizontal Stabilizer Corrosion by visual inspection IAW Socata SB 10-152 amd 1, no defects noted NID 10/2023									
Maintenance Release The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1687-09-2017, Dated 10/1/2017.									
DATE: 10/1/2017		SIGNED: 		Work Order: 1687-09-2017					
		Chris Tharp, IA: 2755348AP		Printed by EBis 3 (datcomedia.com)					
A reporter Carried forward.									

Durée totale des vols : depuis dernière R.G. :
 Total flying time since last major overhaul

depuis fabrication :
 Since manufacture

MAKE Socata
MODEL TB-20
S/N 655
REG NO N20GU
WORK ORDER
1858-08-2018

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE 9/18/2018
A/C TSN 2742 53
TACH 2742 52

50

Airframe Entries

(1) Complied with annual inspection per FAR43(app d). Replaced induction air filter with new BA7112 Air filter... (5) Complied with ELT inspection FAR91.207(d). ELT battery expires: August 2021.... (6) Removed and replaced pneumatic filter with new.... (9) Replaced #5 cylinder bottom lead spring with new.... (11) Complied with AD2015-19-07 fuel injector lines by visual inspection, no defects noted.... (12) Complied with AD2003-04-03 Aileron gimbal joints by visual inspection, no defects noted.... (13) Complied with AD2001-23-04 Rudder hinge cracks by visual inspection, no defects noted.... (14) Removed and replaced L/S and R/S brake linings with new.... (15) Installed new molex plug on the tail cone NAV light.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1858-08-2018, Dated 9/18/2018.

DATE: 9/18/2018

SIGNED:

Chris Sharp, IA, 2755348AP

Work Order: 1858-08-2018

Printed by EBis 3 (dalcomedia.com)

Signature réparateur
nisme de contrôle

signature of overhauler
controlling Authority

TRANSIERRA
TECHNOLOGY

N20GU

Tach time:2743.80

Performed biannual pitot/static/transponder/encoder system test and found it to meet 91.411, 91.413 and appendixes E and F. Certified to 20'000 ft. Results on file CRS DD3R445L.


***END**

Details of work accomplished are on file at this agency under W/O 15666

Authorized Signature _____ Date 09/21/2018

FAA REPAIR STATION # DD3R445L 4130A AVIATION DR MADERA, CA 93637 (559) 675-8320

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
				Report Brought forward .					
MAKE Socata MODEL TB-20 S/N 655 REG NO N20GU WORK ORDER 1961-05-2019		C AND T Aviation INC 4130 Aviation Drive Madera, ca 93637 Phone 559-675-0183				DATE 5/8/2019 A/C TSN 2794 1 TACH 2794 09			
Airframe Entries (1) Removed all three landing gear struts, disassembled, cleaned and inspected struts. Reassembled struts using new seals and serviced with AS4 hydraulic fluid and nitrogen.									
Maintenance Release The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1961-05-2019, Dated 5/8/2019.									
DATE: 5/8/2019		SIGNED: 		Work Order: 1961-05-2019					
MAKE Socata MODEL TB-20 S/N 655 REG NO N20GU WORK ORDER 2019-09-2019		C AND T Aviation INC 4130 Aviation Drive Madera, ca 93637 Phone 559-675-0183				DATE 10/7/2019 A/C TSN 2831 96 TACH 2831 97			
Airframe Entries (1) Complied with annual inspection per FAR43(app d). Replaced induction air filter with new BA7112 ... (5) Complied with ELT inspection FAR91.207(d). ELT battery expires: August 2021... (6) Replaced pneumatic filters with new as necessary... (9) Complied With AD 2015-19-07 Fuel injector lines. no defects noted NID 100hrs TIS... (10) Complied with AD 2005-12-06 Impulse coupling inspection by replacement of Magneto and impulse coupling NID ACTT: 3331 98... (11) Complied with AD 2001-23-04 - Rudder hinge cracks. by visual inspection method. No defects noted NID 12 calendar months... (12) Complied with AD 2003-04-03 Aileron gimbal joints. by inspection, no defects noted. NID 100 hrs TIS... (14) Replaced left and right door opening struts with new 200 N7070780005... (15) Replaced left and right brake discs and linings with new ... (16) Replaced Right main tire with new P/N 156E66-4 FCIII 15-6-6 ... (17) Replaced Oil Pressure Transmitter with new PN: 6025647221, ground ran aircraft ops check normal.									
Maintenance Release The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2019-09-2019, Dated 10/7/2019.									
DATE: 10/7/2019		SIGNED: 		Work Order: 2019-09-2019					
Durée t Total fi		Chris Tharp, IA 2755348AP		Printed by EBis 3 (datcomedia.com)					

MAKE Socata
MODEL TB-20
S/N 655
REG NO N20GU
WORK ORDER
2189-11-2020

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE 12/8/2020
A/C TSN: 2892 7
TACH: 2892 69

51

Airframe Entries

(1) Complied with annual inspection per FAR43(app d). Replaced induction air filter with new BA7112.... (5) Complied with ELT inspection FAR91.207(d). ELT battery expires August 2021.... (6) Removed and replaced pneumatic filters with new.... (7) Removed and replaced fuel cap o-rings with new.... (8) Removed and replaced nose wheel bearings and races with new.... (9) Removed and replaced L/S and R/S brake linings with new.... (10) Troubleshot lower beacon to corroded connector, cleaned connector and lube, ops check good.... (11) Troubleshot annunciator light to broken connector, removed light assy, replaced connector with new and reinstalled. Ops check good.... (12) Removed stabilator from aircraft, replaced left stabilator hinge support with new PN: TB20 34021003. Reinstalled stabilator onto aircraft.... (13) Lubed flap actuator jackscrew, cycled flaps, no defects noted.... (14) Complied With AD 2015-19-07 Fuel injector lines, no defects noted NiD 100hrs TIS.... (15) Complied with AD2001-23-04 Rudder hinge cracks by visual inspection, no defects noted.... (16) Complied with AD 2003-04-03 Aileron gimbal joints, by inspection, no defects noted. NiD 100 hrs TIS.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2189-11-2020. Dated 12/8/2020

DATE: 12/8/2020

SIGNED:

Chris Sharp, IA: 2755348AP

Work Order: 2189-11-2020

Printed by EBis 3 (dalcomedia.com)

3-15-20

NEW LEATHER SEATS INSTALLED

\$4406.53

TACH:

28602

MAKE Socata
MODEL TB-20
S/N 655
REG NO N20GU
WORK ORDER
2331-09-2021

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE 9/17/2021
A/C TSN: 2923 93
TACH: 2923 92

Airframe Entries

(1) Replaced ELT Battery with new E-04 battery. Inspected ELT iaw FAR91.207(d), no defects noted. ELT Battery exp 9/2026

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2331-09-2021. Dated 9/17/2021.

DATE: 9/17/2021

SIGNED:

Chris Sharp, A&P: 2755348AP


Work Order: 2331-09-2021

Printed by EBis 3 (dalcomedia.com)

et — Signature réparateur
Organisme de contrôle
and signature of overhauler
of controlling Authority




SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings
				Départ Departure	Arrivée Arrival				
MAKE Socata MODEL TB-20 S/N 655 REG NO N20GU WORK ORDER: 2378-12-2021 C AND T Aviation INC 4130 Aviation Drive Madera ca 93637 Phone: 559-675-0183 DATE 3/9/2022 A/C TSN 2954 07 TACH 2954 06									
Airframe Entries (1) Complied with annual inspection per FAR43(app d). Replaced induction air filter with new BA7112.... (5) Complied with ELT inspection FAR91 207(d). ELT battery expires September, 2026.... (6) Removed and replaced L/S and R/S brake linings with new.... (7) Replaced instrument air filters.... (8) Cleaned firewall forward engine and cowling.... (9) Cleaned possible spot of corrosion on right wing spar about 4 ft from end of wing on aft side of spar.... (11) Replaced insight cht probe on cylinder 4. Ground ran aircraft, no defects noted.... (12) Replaced missing rivets on wingwalk area on both left and right side.... (14) Replaced missing rivets on instrument panel support with appropriate fasteners.... (16) Replaced both rivets on left door at lift strut attachment point.... (17) Adjusted stall warning vane to prevent from sticking and lubed.... (21) Complied with AD2001-23-04 Rudder hinge cracks by visual inspection, no defects noted. NID 12/2022.... (22) Complied with AD 2003-04-03 Aileron gimbal joints by visual inspection in accordance with the Accomplishment Instructions in Socata TB Aircraft Mandatory Service Bulletin SB 10-130 27, dated April 2002, no defects noted. NID ACTT: 3049 32									
Maintenance Release The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2378-12-2021, Dated 3/9/2022									
DATE: 3/9/2022 SIGNED:  Work Order: 2378-12-2021 Chris Sharp, IA 2755348AP Printed by EBis 3 (datcomedia.com)									
A reporter Carried forward.									
Durée totale des vols : depuis dernière R.G. : depuis fabrication : Total flying time since last major overhaul Since manufacture									

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

52

Dates Date	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Cachet — Signature réparateur Organisme de contrôle Stamp and signature of overhauler and of controlling Authority
---------------------------------	---	---

WO: 16074		Airframe - page 1 of 1	
			
Transierra Technology - 4130 Aviation Dr - Madera, California 93637 - 559-675-8320 - CRS# DD3R445L			
N20GU tach: 2949.31	SOCATA, TB-20 TRINIDAD, S/N: 655	December 30, 2021	
Performed pitot/static/transponder/encoder system test to find it meets all FARs 91.411, FARs 91.413 CFR appendixes E and F. Aircraft certified to 20,000Ft, Aircraft system meets all FAA requirements. Results on file CRS DD3R445L. Aircraft Tested with Laversab 6250 Rev A SN: 82680 and IFR 6000 SN: 104001361.			
With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Transierra Technology under work order: 16074.			
Chris Tharp CRS DD3R445L 			

MAKE Socata
 MODEL TB-20
 S/N 655
 REG NO N20GU
 WORK ORDER:
 2378-12-2021

C AND T Aviation INC
 4130 Aviation Drive
 Madera, ca 93637
 Phone: 559-675-0183

DATE 3/9/2022
 A/C TSN 2954 07
 TACH 2954 06

Airframe Entries

(26) Installed new wing root seals and new wing walk on left and right wings.... (38) Installed new taxi/landing light lense cover on left side.... (39) Installed new nav light lense cover on left side.... (40) Replaced left side main gear down indicator connector.... (41) Resealed front nose strut and serviced with nitrogen.... (42) Installed new pre cut carpet kit from SCS interiors P/N FW-SMK-TB10.... (43) Resealed parking brake valve as per parker CM60-5 overhaul instructions.... (44) Resealed left side main and front nose hydraulic landing gear actuators. Performed landing gear check with aircraft on jacks. No defects noted.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2378-12-2021, Dated 3/9/2022.

DATE: 3/9/2022

SIGNED:




Chris Tharp, IA 2755348AP

Work Order: 2378-12-2021

Printed by EBis 3 (datcomedia.com)

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

53

Dates	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol	Cachet — Signature réparateur Organisme de contrôle
Date	Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Stamp and signature of overhauler and of controlling Authority
2022		
12/2	SOCATA TB20 N20GU S/N 655 DEC. 2, 2022 TACH TIME-3017.62 AIRCRAFT TOTAL TIME-3017.62 REMOVED EXISTING INSIGHT INSTRUMENT CORP. ENGINE TEMPERATURE INDICATOR, MODEL# 603 AND INSTALLED AN INSIGHT INSTRUMENT CORP. UPGRADE G3 ENGINE TEMPERATURE INDICATOR P/N 610C-001. THIS INSTALLATION INCLUDES PRE-EXISTING CHT AND EGT TEMP SENDERS, NEW OIL PRESSURE AND OIL TEMPERATURE SENDERS, OAT SENSOR, FUEL FLOW / TOTALIZER SENSOR, VIBRATION SENSOR, RPM PICKUP SENSOR CABLING AT RIGHT P-LEAD LOCATION P1 AND P2 HARNESS KITS AND CONNECTORS. THIS INSTALLATION ACCOMPLISHED IN ACCORDANCE WITH INSIGHT INSTRUMENT CORP STC# / AML SA02930NY, INSIGHT INSTALLATION MANUAL 070906 REV. 1.6 PAGES 1-54. ICA INSTRUCTIONS CAN BE FOUND WITHIN INSIGHT DOCUMENT 610C-ICA ISSUE 4, DATED JAN. 19, 2012. FAA FOR 337 COMPLETED THIS DATE. AIRCRAFT EQUIPMENT LISTING / WEIGHT AND BALANCE DATA REVISED TO REFLECT THIS CHANGE. FLIGHT MANUAL SUPPLEMENT INSTALLED IN AIRCRAFT POH. SYSTEM FUNCTION CHECKS ACCOMPLISHED AND FOUND TO BE SATISFACTORY. DAVID M PAGE A&P 3130153 IA 	

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	Pilote Pilot	Nombre membres d'équi- page Number of Crew	Voyage Journey	Heures Times		Durée du vol Duration of Flight	Kilo- mètres parcourus Distance Flown Kilo- metres	Nombre de passagers Number of Passengers	Nombre d'atterris- sages Number of Landings		
				Départ Depart- ture	Arrivée Arrival						
2022				Report							
12/19				Brought forward.							
SOCATA TB20 N20GU S/N 655 12/19/2022 TACH TIME-3017.82 REMOVED EXISTING INSIGHT G3 TEMPERATURE / PRESSURE INDICATOR AND INSTALLED AN INSIGHT G4 INDICATOR, P/N 1200C-001, SERIAL# 40660. ALL PROBES, SENDING UNITS AND TRANSDUCERS REMAIN THE SAME. COMPETED FORM 337 TO DOCUMENT THIS INDICATOR CHANGE, AIRCRAFT EQUIPMENT LIST / WEIGHT AND BALANCE DATA REVISED, G4-ICA AND FLIGHT MANUAL SUPPLEMENT G4-FMS ISSUE 1 PROVIDED TO OWNER. CORRESPONDING STC REMAINS THE SAME, SA02930NY AS DOES THE INSTALLATION MANUAL, 070906 REV. 1.6. FUNCTION CHECKED INDICATOR AND FOUND SATISFACTORY. DAVID M PAGE A&P 3130153 <i>David M Page</i>											

**** FAA/PMA APPROVED PART - PQ2056CE ****

ITEM: DOOR WINDOW - NO VENT HOLE-LH (SC15 GRAY)

PART NUMBER: **SC-W/G-2437-187-LH**

AIRCRAFT MAKE AND MODEL: SOCATA - Groupe Aerospeciale, TB 9, TB 10, TB 20
TB 21, TB 200

SERIAL NUMBERS: 1 thru 1999 except 1900 - (Pre-MOD 151)

REPL PN: TB1Q 25030100, TB1Q 25030106, TB1Q 25030102, TB1Q 25030108

MANUFACTURE DATE: 09-27-2022 MANUFACTURE CODE: **1298883**

FOR CONTINUED AIRWORTHINESS SEE AIRCRAFT P.O.M. OR SERVICE MANUAL

PLEASE KEEP THIS TAG FOR YOUR LOG BOOK.

GREAT LAKES
AERO PRODUCTS, INC.
FLINT, MI

APPROVED
Great Lakes Aero
Products, Inc.

(810)-235-1402
www.glapinc.com
915 Kearsley Park Blvd
Flint, MI 48503

RNW Aircraft Services

Rocklin, CA 95765
Phone 530-314-9458

MAKE/MODEL : SOCATA TB20 REGISTRATION : N20GU

SERIAL NO. : 655

AIRCRAFT TAC : 3017.82

AIRFRAME TT : 3017.82

Date: 12/21/2022 AIRFRAME MAINTENANCE LOGBOOK ENTRY.

REMOVED PILOTS SIDE WINDOW DUE TO A SMALL CRACK FORMED ON VENT WINDOW.
REPLACED PILOTS WINDOW WITH PART NUMBER SC-W/G-2437-187-LH **SC15 GRAY** (NO VENT
HOLE) FOR TB20 FROM GREAT LAKES AERO. (FAA/PMA APPROVED #PQ2056CE) MANUFACTURE
DATE OF 09-27-2022, CODE: 1298883. SERIAL NUMBERS 1 THRU 1999. (PRE-MOD 151)

INSTALLED THE NEW WINDOW IN ACCORDANCE WITH THE SOCATA MAINTENANCE MANUAL AND
APPLICABLE AC 43 SERIES. THE NEW WINDOW DID NOT REQUIRE ANY TRIMMING, 100% CLEAR
SILICONE SEALANT WAS USED BETWEEN THE FRAME AND WINDOW FOR PROPER SEALING.
UTILIZED 100% BLACK SILICONE SEALANT FOR THE OUTSIDE BEAD. 3/16 ALUMINUM RIVETS
WERE USED TO SECURE THE WINDOW TO THE FRAME FROM PREVIOUSLY DRILLED HOLES ON
THE ORIGINAL INSTALLATION.

REFER TO APPROVED TAG ENCLOSED IN THE LOGBOOK.

END OF ENTRY

ALL WORK DONE IN ACCORDANCE WITH SOCATA MAINTENANCE MANUALS, AND AC 43.13-1B,
SECTION 3 TRANSPARENT PLASTICS, WINDOW INSTALLATION.

Signed

Randy L. Sharp
Randy L. Sharp A&P 2838871

Date: 12/21/2022

Partielles ou générales

à la machine overhaule

Cachet — Signature réparateur

Organisme de contrôle

Stamps and signature of overhauler
authority

SERVICE DE L'AVIATION - AIRCRAFT RECORD



Sky Trails Aviation | 2400 Rickenbacker Way | Auburn | CA | 95602

Date: 04-21-2023 **Logbook:** Airframe **Tail Number:** N20GU


Tach: 3029.27 **Hobbs:** ATT: 3029.27 **Model:** TB-20 TRINIDAD **Serial:** 655

Aircraft: The aircraft identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below.

Repairs / Maintenance

- This Aircraft was opened and serviced for Annual Inspection in accordance with a checklist conforming to FAR 43, Appendix D. Repacked all wheel bearings. Checked all fuel system filters. Replaced vacuum system filters. Charged aircraft battery. Lubricated all landing gear points with Aeroshell 22 grease. Performed landing gear retraction tests, including emergency extension.
- Replaced nose gear down assist SACHS rods with factory new parts supplied by customer.
- Replaced flap circuit breaker with new p/n 7277-2-10 Klaxon circuit breaker.
- Complied with AD 91-05-02 (Eff. 03/25/1991) by inspection of fuselage frame "0" for cracking, no cracks noted. Observed service kit was previously installed. Reviewed logbooks and found previous compliance on 05/20/2013 when reinforcement kit OPT10915200 was installed. This installation permanently complies with AD 91-05-02. This AD is no longer recurring.
- Complied with AD 2001-23-04 (Eff. 01/04/2001) by inspection of lower rudder hinge for cracks, none found. Next due 12 calendar months, or 04/2024.
- Complied with AD 2003-04-03 (Eff. 04/07/2003) by inspection of aileron gimbal joints, no defects noted. Next due at 3129.27 hours.
- Complied with AD 2015-24-03 (Eff. 01/01/2016) by inspection of stabilator spar for corrosion, none found. Next due for inspection 4/2029.
- Removed, cleaned and serviced ailerons, flaps, and rudder hinge bearings and rod ends with Aeroshell 22 grease per maintenance manual.
- Replaced fuel drain valve p/n TB10 52050001, and O-Ring p/n Z00.N7423550073 on left wing.
- Sealed 3 each fuel tank access panel screws in left wing and 2 each rivet in upper right wing fuel tank skin with CS3204B1/2 sealant.
- Installed 10-32 thread inserts into left main gear wheel for hub cap attachment.
- Resealed left brake caliper and bleed brake system. Ops check good, no leaks noted..
- Removed right main gear actuator, disassembled, cleaned, inspected and replaced old seals and rings using new seal kit p/n Z00.N6028207226. Work was accomplished in accordance with Component Maintenance Manual p/n TB20 47007.
- Replaced old alternator cooling duct with 12 inches of SCAT-4 tubing.
- Reinstalled broken off pilots side instrument panel cover attachment tab with nut plate on outboard side.
- Replaced co-pilot instrument panel outboard shock mount with new p/n Z00.N7677701293 mount.
- Sealed wiring pass through holes at firewall with black RTV.
- Inspected and tested ELT in accordance with FAR 91.207(d). Battery next due for replacement Sept. 13, 2026.
- Replaced broken ground static discharger p/n Z00.N4740492150 on right main gear.

I certify that this Aircraft was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition.

Signature: 

Robert J. Burnett | AP 3633440 I.A.

A reporter

Carried forward.

Durée totale des vols : depuis dernière R.G. :
Total flying time since last major overhaul


depuis fabrication :
Since manufacture

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

55

Dates Date	Dét Program Ta Type	wo: AIRMETRICS-2023-025 Airframe - page 1 of 2 AirMetrics, Inc - 2400 Rickenbacker Way - Auburn, CA 95602 - (530) 718-0607 - N/A#:	ur uler y
		N20GU SOCATA, TB-20 TRINIDAD, S/N: 655 May 23, 2024 TACH: 3056.82 Removed Bendix King KAP 150 Autopilot System with Electronic Pitch Trim including Pitch, Roll, and Pitch Trim Servos, aft stabilator pitch trim cable extension, KC 191 Flight Control Computer, KG 258 Horizon Gyro, and KG 107 Directional Gyro. Removed Airborne 211CC Vacuum System including pump, regulator, filter, and hoses. Removed Standby Vacuum System motor, pump, and switch. Removed Garmin GI 106A CDI. Removed Bendix King KI 208A CDI. Removed Bendix King KT 76A Mode C transponder. Removed Concorde RG-25XC Sealed Lead Acid Battery. Installed new Concorde RG-25XC Sealed Lead Acid Battery. Installed Superior SL60430 Vacuum Pump Cover and 07-12760 Gasket. Installed NuLite LW2014 Instrument Lighting System instrument lights for Airspeed, Altimeter, Tachometer, and Manifold Pressure instruments IAW AC 43.13-1B, Chapter 11, all sections. Installed Bendix King KT76C Transponder as a slide-in replacement for removed Bendix King KT76A Transponder. Installed two Garmin GI 275 ADAHRS Multi-Function Display Systems as ADI and HSI, P/N 011-04489-10, and Garmin GMU 11 Magnetometer In Accordance With Garmin GI 275 Master Drawing List 005-01208-41, Revision 23, dated February 1, 2024, and Garmin GI 275 Part 23 AMI STC Installation Manual 190-02246-10, Revision 13, dated May 2022. Interfaced GI 275s to Garmin GTN 750 Navigator as GPS 1/NAV 1 and to Bendix King KX 155 as NAV 2. This installation is approved by STC SA02658SE. Installed Garmin GFC 500 Autopilot with Electronic Stability Protection in accordance with Garmin GFC 500 Master Drawing List 005-01264-00, Revision 90, dated May 1 2024, Garmin GFC 500 Installation Manual 190-02291-00, Revision 24, dated Feb 15, 2023, and Socata TB20/21 GFC 500 Install Manual Addendum 190-02291-72, Revision 1, dated Feb 1, 2021. This installation consists of a Garmin GMC 507	
		CONTINUED NEXT PAGE →	

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Dates Date	wo: AIRMETRICS-2023-025 Airframe - page 2 of 2  AirMetrics, Inc - 2400 Rickenbacker Way - Auburn, CA 95602 - (530) 718-0607 - N/A#: '	Nombre d'atterris- sages Number of Landings
	Autopilot Mode Controller, a Garmin GSA 28 Roll Servo, a Garmin GSA 28 Pitch Servo, and a Garmin GSA 28 Pitch Trim Servo. This installation is approved by STC SA01866WI. Re-Rigged stabilator pitch trim in accordance with Socata TB 20 Maintenance Manual, P/N Z00.18010320E0R16, Revision 16, dated 1/15/2004, section 27-30-03. Replaced pilot control wheel main bolt (P/N Z00.N5101229339), washers (P/N Z00.N5701039290), and nut (P/N Z00.N5401458300) in accordance with Socata TB 20 Maintenance Manual, P/N Z00.18010320E0R16, Revision 16, dated 1/15/2004, section 27-30-01. Printed AFMS for Garmin GI 275 Multifunction Instrument System, Document 190-02246-12, Revision 12, dated 2/2/2024 and placed in aircraft. Printed Instructions for Continued Airworthiness, Section 3 of Garmin GI 275 Part 23 AML STC Maintenance Manual, Document 190-02246-11, Revision 8, dated 2/2/2024, and placed in aircraft. Printed AFMS for Garmin GFC 500 Autopilot with ESP, As Installed in Socata TB20/21, Drawing Number 190-02291-73, Revision 2, dated 4/21/2023, and placed in aircraft. Printed Instructions for Continued Airworthiness, Section 4 of Garmin GFC 500 Autopilot with ESP Part 23 AML STC Maintenance Manual, Document 190-02291-01, Revision 12, dated 1/31/2024 and placed in aircraft. Computed new Weight and Balance and updated Aircraft Equipment List. Filed FAA Form 337(s). Robert J Burnett, AP 3633440 IA 	
	A reporter Carried forward.	
Durée totale des vols : depuis dernière R.G. : Total flying time since last major overhaul	depuis fabrication : Since manufacture	

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

56



Sky Trails Aviation | 2400 Rickenbacker Way | Auburn | CA | 95602
 Date: 07-01-2024 Logbook: Airframe Tail Number: N20GU
 Tach: 3056.88 Hobbs: ATT: 3056.88 Model: TB-20 TRINIDAD Serial: 655

Aircraft: The aircraft identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below.

Repairs / Maintenance

- This Aircraft was opened and serviced for Annual Inspection in accordance with a checklist conforming to FAR 43, Appendix D. Repacked all wheel bearings. Charged aircraft battery. Checked and cleaned fuel screens. Lubricated all landing gear points. Performed landing gear swings, including emergency extension. Checked and serviced brake fluid reservoir. Checked fuel system filters. Replaced fuel strainer O-ring. Checked all AD's through Avant release 2024-12, see AD list this date for details.
- Replace nose wheel bearing cone and cup with new Timken P/N: LM67048-20629 cone and P/N: LM67010-20629cup.
- Replaced broken zip ties on engine mount for engine monitor harness with Adell clamps.
- Stop drilled cracks in pilots door frame near shock strut attachment.
- Replaced left brake linings with new Cleveland 066-10600 linings using 105-00200 rivets.
- Inspected rudder trim not moving full travel, found aft push-pull rod at tab bent. Straightened rod and checked travel, ops check good.
- Complied with AD 2001-23-04 (Eff.01/04/2002) by inspection of lower rudder hinge for cracks, none found. AD next due for compliance 06/2025
- Tested ELT in accordance with FAR 91.207(d).
- Removed and installed pilot's right brake master cylinder for inspection. Replaced the 2 shaft o-rings in master cylinder p/n MS28775-011. Bleed right brake system and ops check good.
- Troubleshoot alternator out light always on. Confirmed alternator is charging at 14 volts. Inspected alternator out sensor pc board, no defects noted. Cleaned electrical wiring contacts on board. Reassembled pc board cover and tested light. Light properly working at this time.

I certify that this Aircraft was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition.

Signature:

Robert J. Burnett | AP 3633440 I.A.



AirMetrics, Inc. • 2400 Rickenbacker Way • Auburn, CA 95602 • (530) 718-0607 • N/A#:

N20GU
TACH: 3069.6

SOCATA, TB-20 TRINIDAD, S/N: 655

August 13, 2024

Installed Garmin GTP 59 Outside Air Temperature (OAT) probe on aircraft belly, forward of transponder antennas, and interfaced to GI 275 in the ADI position in accordance with (IAW) Garmin GI 275 Part 23 AML STC Installation Manual, Document 190-02246-10, Revision 19, dated May 2024, Section 4.6.2 (installation) and Figure B2 (wiring). Re-terminated instrument panel illumination for Visor Lights (potentiometer output to Fluorescent ballast), EIS overhead lighting, compass lighting, Transponder, and Audio Panel illumination to the instrument lighting terminal strip located on the left side of the rear instrument panel. Illumination wiring completed IAW AC 43.13 1B, Chapter 11, all sections. Updated ADI and HSI GI 275 Main Software from Version 3.01 to Version 3.20 IAW Garmin Service Bulletin 24030 Rev B and Garmin GI 275 Part 23 AML STC Installation Manual, Document 190-02246-10, Revision 19, dated May

Test Altitude	Scale Error	Friction Error	Encoder	Leak Acft/Case	Hysteresis
-1000	0		-1.0	8901200	
0	-1.0		-0		
500	-1.0		-1		
1000	-1.0	2.0	1.0		
1500	-1.0		1.0		
2000	0	2.0	2.0	50%	10h 42.0
3000	0	2.0	7.0	40%	8h 11.0
4000	0		4.0	After Effect	0 Check Pilot Heat
5000	-2.0		3.0	Baro. Scale Error (± 25 ft.)	
6000	-3.0		6.0	28.10	-1727
8000	-5.0		8.0	28.50	-1340
10000	-6.0	2.0	10.0	29.00	-863
12000	-8.0		14.0	29.50	-392
14000	-7.0		15.0	29.92	0
15000	-7.0	2.0	16.0	30.50	+531
16000	-8.0		16.0	30.90	+893
18000	-8.0		16.0	30.99	+974
20000	-9.0	3.0	21.0	Aircraft #	42064
22000				Date Tested:	8/4/14
25000				Technician:	
30000				Inspector:	
35000					
40000					
45000					
50000					

Tested in compliance with Appendix E, Part 43, F.A.R 91.411
 Tested to: 20h ft. W.O. #: 25726

Precision Static Testing FAA CRS# QJAR856X

PILOT / FIRST OFFICER / STAND-BY

Form 1A

s required
d by §
§ 91.217,
FR Part

ward

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

57



09/01/2025 RB
 Sky Trails Aviation | 2400 Rickenbacker Way | Auburn | CA | 95602
 Date: 08-26-2025 Logbook: Airframe Tail Number: N20GU
 Tach: 3117.85 Hobbs: ATT: 3117.85 Model: TB-20 TRINIDAD Serial: 655

Aircraft: The aircraft identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below.

Repairs / Maintenance

- This Aircraft was opened and serviced for Annual Inspection in accordance with a checklist conforming to FAR 43, Appendix D. Repacked all wheel bearings. Charged aircraft battery. Checked fuel system filters. Lubricated all flight control and landing gear points. Performed landing gear retraction tests, including emergency extension. Checked and serviced brake fluid reservoir. Checked all AD's through this date using TBX AD system.
- Checked right and left fuel tank vent tubes for obstructions, none found. Blew out lines to verify no blockages.
- Installed riv-nut and screw to secure pilots door lower forward section of upholstery panel to door.
- Secured wiring under instrument panel that was being hit by yoke when fully pulled back.
- Bleed right brake system and serviced system with MIL-H-5606 hydraulic fluid. Operational checks good.
- Secured pitot tube heat wiring in wing to prevent chafing rib in wing.
- Cleaned and lubricated throttle and propeller controls, operational checks good.
- Tested ELT in accordance with FAR 91.207(d).
- Complied with AD 2001-23-04 (Eff. 01/04/2002) by inspection of lower rudder hinge for cracks, none found. AD next due for compliance 08/2026.
- Complied with AD 2003-04-03 (Eff. 04/09/2003) by inspection of aileron control gimbals, no issues noted. AD next due for compliance at 3217.85 tach

I certify that this Aircraft was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition.

Signature:

Robert J. Burnett | AP 3633440 LA.

The Standard
ENGINE LOG

ASA-SE-2

Engine Record General Information

Manufacturer Lycoming Model I0-540-C4D5D
Serial L-23149-48A Type Certificate _____

This engine is currently installed in aircraft: N206U

Minimum Octane Fuel _____ Oil Grade Summer _____ Winter _____

Magneto Time _____ Point Setting _____ Firing Order _____

Spark Plug Gap _____

Manufacturer's Recommended Overhaul at 2000 hours

YEAR
20 _____
DATE

RECORDING
TACH
TIME

T
F

CERTIFIED ENGINE OVERHAUL

EXODUS AIR SERVICE, CORP.

4555 WEST AVE "G"

LANCASTER, CA 93536

661-942-6489

661-942-0012 FAX

WJF

F.A.A REPAIR STATION #XXOR712L

MAKE Lycoming

MODEL IO-540-C4D5D

S/N L-23149-48A

HOURS SINCE MAJOR OVERHAUL 0.00

THIS ENGINE WAS OVERHAULED AND INSPECTED IN
ACCORDANCE WITH CURRENT FEDERAL AVIATION
REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE

PERTINENT DETAILS OF
THE REPAIR ARE ON FILE UNDER

WORK ORDER NUMBER 773

DATE 04-19-2013

AUTHORIZED SIGNATURE

TOTAL TIME ON ENGINE

BEFORE OVERHAUL 2217.74

pairs and Alterations

nd Certificate Number of
for other specific entries.)

May 2, 2013

[EXODUS AIR SERVICE]

4555 West Ave "G" Ste#6 (WJF)
Engine M/N IO-540-C4D5D


Lancaster, California 93536
S/N L-23149-48A

Phone (661) 942-6489
Eng. T.T. 2217.74

TSMO 0.00

W/O 773

This engine was disassembled, cleaned, inspected Major overhaul and re-assembled after the following work: Connecting rods, Camshaft, Crankshaft overhauled by Aircraft Specialties Services, Inc. Crankcase repair by Divco, Inc. and all engine parts were inspected by Active Magnetic, Sun Valley, CA. Fuel system overhauled by D&G supply. Alternator, Starter overhauled by Aero Accessories. Cylinder's overhauled by Exodus Air Service Inc. Magneto's clean, inspected overhauled & bench tested. Plating services by Aero Chrome. The following parts were replaced at engine assembly: LW13792 Crankshaft seal, LW13377 Gasket set, SL72877 Lifter, SL16711A MO6 Main bearings, 65007 Retainer, SL13884 MO6 Main bearings, 61084 Oil pressure spring, 1028-B Oil pressure ball, AN8-14A Crankshaft bolt, AN565B1032H5 Set screw, O5K23463 Oil pump impeller's, AEL11795 Spring inner, LW11800 Spring outer, LW60009 Key intake valve, 17C21191 Key exhaust, LW19001 Exhaust valve, 16R22291PO5 Exhaust guide, 75061 Connecting rod bolt, LW12186 Connecting rod nut, SL13521 Connecting rod bearing's, AEL75089 Piston, LW14078 Piston pin, ST203 Ring set, 74637Rocker arm bushings, AA48103-2 Oil filter, LW12892 Thrust button, LW13790 Rocker shaft, O6B23072 Oil filter gasket, 55k21022 Spacer, O5S21021 Spring, 70484 Screen, 10-400576 Capacitor, 69603 Intake hose, 10-400567 Bearing, 10-382585 Contac Assy, 10-391213 Screw, 10-50752 Felt washer, 10-163374 Felt strip, LW15592-8-28 Clamp, LW15592-5-05 Clamp, STD-2180 Hose, 53E22144 Vernatherm, 31C-12 Studs, LW 14995, 10-90788-5 Woodruff key, AB682016 Gear kit, 72965 Roller, AEL73810 Bushing, LW13923 Bushing, LW14820 Counterweight circlips, SL71903 Bushing, SL71907A Washer, SL72797 Roller, MS29512-10 O ring, MS29512-06 O-ring, 77611, Engine returned to service.



Juan Paiz

F.A.A REPAIR STATION #XXOR712L

YEAR
20
DATE

ENGINE MODEL:
IO-540-C4D5D
ENGINE S/N: L-23149-48A
REG. NO: N20GU
WORK ORDER:
1076-01-2013

Barber Aviation

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 5/20/2013
A/C TSN: 2217.75
ENG TT: 2217.74
TSMOH: 0
TACH: 2217.74

ns
of
S.)

Engine Entries

(2) Complied with 100hr inspection per FAR43(app d). Engine removed and replaced after overhaul by Exodus Air. Engine serviced with 12qts AS100 oil. Engine washed and ground ran, no defects noted.... (8) Complied with AD2011-26-04 Fuel injector lines by visual inspection, no defects noted. NID ACTT: 2317.75... (11) Removed and replaced alternator belt with new 37A19773-376 belt and tensioned.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1076-01-2013, Dated 5/20/2013.

DATE: 5/20/2013

SIGNED:



Chris Tharp, A&P: 2755348AP

Work Order: 1076-01-2013

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL:
IO-540-C4D5D
ENGINE S/N: L-23149-48A
REG. NO: N20GU
WORK ORDER:
1132-08-2013

Barber Aviation

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 8/15/2013
A/C TSN: 2250.71
ENG TT: 2250.7
TSMOH: 32.96
TACH: 2250.7

Engine Entries

(1) Changed oil and filter CH48103-1, filter cut and inspected, no defects found. Engine serviced with 12qts AS100W Plus. Engine washed and ground ran no defects noted.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1132-08-2013, Dated 8/15/2013.

DATE: 8/15/2013

SIGNED:



Chris Tharp, A&P: 2755348AP

Work Order: 1132-08-2013

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL:
IO-540-C4D5D
ENGINE S/N: L-23149-48A
REG. NO: N20GU
WORK ORDER:
1222-05-2014

Barber Aviation

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 6/4/2014
A/C TSN: 2317.05
ENG TT: 2317.04
TSMOH: 99.3
TACH: 2317.04

Iterations
Number of
fic entries.)

Engine Entries

(2) Complied with 100hr inspection per FAR43(app d). Changed oil and filter CH48103-1, filter cut and inspected, no defects noted. Engine serviced with 12qts AS100w Plus. Engine washed and ground ran, no defects noted.... (4) Complied with compression check as follows 1-76 2-76 3-76 4-78 5-78 6-74/80psi.... (11) Complied with AD2011-26-04 Fuel injector lines by visual inspection of all clamps, no defects noted. NID ACTT: 2417.05

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1222-05-2014, Dated 6/4/2014

DATE: 6/4/2014

SIGNED:



Work Order: 1222-05-2014

Chris Tharp, A&P: 2755348AP

Printed by EBis 3 (datcomedia.com)

[illegible]

YEAR 20 ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

ENGINE MODEL:
IO-540-C4D5D
ENGINE S/N L-23149-48A
REG NO: N20GU
WORK ORDER:
1375-06-2015

Barber Aviation

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 8/3/2015
A/C TSN: 2440 07
ENG TT: 2440 06
TSMOH: 222 32
TACH: 2440 06

Engine Entries

(2) Complied with 100hr inspection per FAR43(app d). Changed oil and filter CH48103-1, filter cut and inspected, no defects noted. Engine serviced with 12qts AS100Wplus, engine washed and ground ran, no defects noted.... (4) Engine compression check # 1-74/80 #2-78/80 #3-76/80 #4-76/80 #5-78/80 #6-76/80.... (12) Complied with AD2011-26-04 Fuel injector lines by visual inspection, no defects noted. NID ACTT: 2540.07

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1375-06-2015, Dated 8/3/2015.

DATE: 8/3/2015

SIGNED:

Chris Tharp, A&P: 2755348AP

Work Order: 1375-06-2015

Printed by EBis 3 (datcomedia.com)

[illegible]

YEAR 20 ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

ENGINE MODEL:

iO-540-C4D5D

ENGINE S/N: L-23149-48A

REG. NO. N20GU

WORK ORDER

16E7-09-2017

Barber Aviation

4130 Aviation Drive

Madera, ca 93637

Phone: 559-675-0183

DATE: 10/1/2017

A/C TSN 2640.43

ENG TT: 2640.42

TSMOH 422.68

TACH. 2640.42

Engine Entries

(2) Complied with 100hr inspection per FAR43(app d). Changed oil and filter CH48103-1, engine serviced with 12qts AS100W. Engine washed and ground ran no defects noted... (4) Complied with compression check as follows 1-74 2-78 3-75 4-74 5-60 6-76/80

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1687-09-2017, Dated 10/1/2017.

DATE: 10/1/2017

SIGNED:

Chris Tharp, A&P: 2755348AP

Work Order: 1687-09-2017

Printed by EBis 3 (datcomedia.com)

YEAR
20
DATE

ENGINE MODEL:
IO-540-C4D5D
ENGINE S/N: L-23149-48A
REG NO: N20GU
WORK ORDER:
1858-08-2018

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 9/18/2018
A/C TSN: 2742 53
ENG TT: 2742 52
TSMOH: 524 78
TACH: 2742 52

rations
nber of
entries.)

Engine Entries

(2) Complied with 100hr inspection per FAR43(app d).... (4) Complied with differential compression check as follows 1-76 2-75 3-76 4-74 5-- 6-75/80... (7) Removed #5 Cylinder due to burnt valve and installed new Lycoming cylinder.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1858-08-2018, Dated 9/18/2018.

DATE: 9/18/2018

SIGNED:



Chris Tharp, IA: 2755348AP

Work Order: 1858-08-2018

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL:
IO-540-C4D5D
ENGINE S/N: L-23149-48A
REG NO: N20GU
WORK ORDER:
2019-09-2019

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 10/7/2019
A/C TSN: 2831 98
ENG TT: 2831.97
TSMOH: 614 23
TACH: 2831.97

Engine Entries

(2) Complied with 100hr inspection per FAR43(app d). Changed oil and filter CH46103-1, engine serviced with 9qts AS100WPLUS. Engine washed and ground ran no defects noted.... (4) Complied with diferential compression check as follows 1-68 2-74 3-70 4-76 5-78 6-72/80... (13) Removed Magneto and replaced with Kelly Overhauled unit PN: 10-682560-11R SN: H-06556. Timed magneto to engine, ground ran aircraft, ops check good.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2019-09-2019, Dated 10/7/2019.

DATE: 10/7/2019

SIGNED:




Chris Tharp, IA: 2755348AP

Work Order: 2019-09-2019

Printed by EBis 3 (datcomedia.com)

YEAR 20 22 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
AUG. 3	3002.77			
				SOCATA TB-20 N20GU S/N 655
				LYCOMING IO-540-C4D5D S/N L-23149-48A
				AUG. 3, 2022 TACH TIME-3002.77
				TROUBLESHOT FAULTY RIGHT SIDE MAGNETO OPERATION, REMOVED MAGNETO, D6LN-3000, S/N H-06556 AND ROUTED TO AERO ACCESSORIES FOR REPAIR. REINSTALLED MAGNETO, D6LN-3000, S/N H-06556 AFTER 500HR INSPECTION AND REPAIR BY AERO ACCESSORIES, CRS# XB2R286L. MAGNETO IMPULSE COUPLING INSPECTION ACCOMPLISHED IN ACCORDANCE WITH AD2005-12-06, NEXT INSPECTION DUE IN 500 HOURS, SEE FAA FORM 8130-3 DATED 29 JUL 2022 FOR MAGNETO REPAIR DETAILS. TIGHTENED LOWER FORWARD CRANKCASE PARTING HALVE AND OIL SUMP SECURING HARDWARE, TIGHTENED INDUCTION ELBOW HOSE CLAMPS AND CYLINDER OIL RETURN LINE HOSE CLAMPS. CHANGED OIL AND FILTER, NEW CH48103-1 FILTER INSTALLED AND 9 QTS AEROSHELL W100 PLUS ADDED, INCLUDING ONE BOTTLE OF CAMGUARD. MAGNETO INSTALLATION ACCOMPLISHED IN ACCORDANCE WITH LYCOMING SI1508C, REFERENCED LYCOMING IO-540 OPERATORS MANUAL FOR REMAINING WORK, GROUND RUNUP, LEAK CHECK SATISFACTORY.
				DAVID M PAGE A&P 3130153 

YEAR 20 <u>22</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
12/2	3017.62			SOCATA TB20 N20GU S/N 655 DEC. 2, 2022 LYCOMING IO-540-C4D5D S/N L-23149-48A TACH TIME-3017.62 INSTALLED THE FOLLOWING COMPONENTS RELATED TO UPGRADING THE EXISTING INSIGHT 603 TEMPERATURE INDICATOR TO A G3, 610C TEMPERATURE INDICATOR TO INCLUDE FUEL FLOW / TOTALIZER SENSOR P/N 1000-004A-3 SERIAL# 269413, NEW HOSE INSTALLATIONS P/N'S 111F417-6S-0070 AND 111F417-6S-0160, STANDBY OIL PRESSURE AND TEMP SENSORS, P/N'S 610C-024 610C-022-1, VIBRATION SENSOR P/N 1000-004V, RPM PICKUP SENSOR INSTALLED AT RIGHT P-LEAD LOCATION. PREVIOUSLY INSTALLED EGT AND CHT TEMP SENDERS P/N'S 2870 AND 2853 REMAIN. SEE FAA FORM 337 AND AIRCRAFT LOGBOOK ENTRY FOR FURTHER DETAILS, INSTALLATIONS ACCOMPLISHED IN ACCORDANCE WITH STC# SA02930NY AND AC43.13.1B,2B GROUND RUNUPS AND LEAK CHECKS ACCOMPLISHED, SYSTEM OPERATIONS FOUND TO BE SATISFACTORY. DAVID M PAGE A&P 3130153 IA 

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	---



Sky Trails Aviation | 2400 Rickenbacker Way | Auburn | CA | 95602

Date: 04-21-2023 Logbook: Engine 1 Tail Number: N20GU

Make: LYCOMING Model: IO-540-C4D5D Serial: L-23149-48A

Tach: 3029.27 TSN: 3029.27 TSMOH: 811.53

Engine: The aircraft engine identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below.

Repairs / Maintenance

- Changed oil and filter. Cut open old filter and inspect, no metal found. Serviced engine with 12 quarts of Aeroshell 100 mineral oil. Serviced, tested and rotated all spark plugs. Checked magneto to engine timing. Compression check results: #1 76/80 #2 78/80 #3 70/80 #4 78/80 #5 78/80 #6 12/80. Checked fuel system filters. Ground runs good, no leaks noted.
- Replaced #6 cylinder with overhauled exchange standard size cylinder assembly from Gibson Aviation. Checked new piston ring end gaps and installed new rings onto original piston after cleaning ring grooves. Cylinder installed with all new seals and gaskets.
- Complied with AD 2015-19-07 (Eff. 11/03/2015) by inspection of fuel injector lines and clamps. No defects noted, next due at fuel injector servicing or clamp replacement.
- Fabricated and installed aft baffle plate attachment bracket for attachment to engine upper case bolt.
- Installed clamps and hardware missing from aft baffle plate right and left attachment points per I.P.C.
- Replaced cylinder #3 and #4 drain back tube hoses with stock MIL-H-6000 3/8 I.D. hose.
- Cleaned engine breather tube and tightened connection hose clamps to prevent oil weeping from breather tube connections.
- Replaced crush gasket p/n MS35769-31 on oil pressure relief valve housing. Ops check good, no leaks noted.
- Replaced #2 and #5 fuel injector lines with new Superior Airparts FAA/PMA p/n SL12098-0-210 Fuel lines. Leak check good, no defects noted.

I certify that this Engine was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition.

Signature: _____

Robert J. Burnett | AP 3633440 I.A.

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	---



09/01/2025 *KB*

Sky Trails Aviation | 2400 Rickenbacker Way | Auburn | CA | 95602

Date: ~~08-26-2025~~ Logbook: Engine 1 Tail Number: N20GU

Make: LYCOMING Model: IO-540-C4D5D Serial: L-23149-48A

Tach: 3117.85 TSN: 3117.85 TSMOH: 900.11

Engine: The aircraft engine identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below.

Repairs / Maintenance

- Changed oil and filter. Cut open old filter and inspect, no metal found. Serviced engine with 10 quarts of Aeroshell W100 plus oil. Serviced all spark plugs. Checked magneto to engine timing. Serviced all fuel injectors. Checked fuel filter screen. replaced induction air filter element. Compression check results: #1 75/80 #2 77/80 #3 77/80 #4 70/80 #5 74/80 #6 76/80. Ground runs good, no leaks noted.
- Checked and cleaned oil pressure transducer wiring connectors, operational checks of oil pressure indicating system good.
- Replaced #2 cylinder intake and exhaust pushrod tube seals.
- Replaced magneto mounting gasket with new LW-12681 gasket. Reset magneto to engine timing.
- Replaced engine breather tube hose with new length of CAT ducting.
- Complied with AD 2015-19-07 (Eff. 11/03/2015) by inspection of fuel injector lines and clamps, no issues noted. AD next due for compliance at 3227.85 Tach.

I certify that this Engine was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition.

Signature: *[Signature]*

Robert J. Burnett | AP 3633440 LA.

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C3YR-1RF/F7693F

PROPELLER S/N PA582B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position Single

PITCH RANGE

Propeller Model HC-C3YR-1RF/E7693F

High/Feather 31

Propeller S/N PA582B

Start Lock NA

Blade Design _____

Low 13

Blade S/N's

Reverse NA

No. 1 L32376

No. 2 L32377

No. 3 L32378

No. 4 _____

No. 5 _____

No. 6 _____

Aircraft Manufacturer Socata

Aircraft Model TB-20

S/N 655

Registration N20GU

Spinner Assembly Part No. _____

Date

PROP MODEL:
HC-C3YR-1RF/F7693F
PROP S/N: PA582B
REG. NO: N20GU
WORK ORDER:
1076-01-2013

Barber Aviation
4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 5/20/2013
A/C TSN: 2217.75
PROP TT: 0
TACH: 2217.74

s,
tions.

Prop Entries

(3) Installed new Hartzell propeller HC-C3YR-1RF/F7693F IAW STC SA01192CH. See FAA337 and revised weight and balance this date. Complied with 100hr inspection per FAR43(app d)

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1076-01-2013, Dated 5/20/2013.

DATE: 5/20/2013

SIGNED: 

Work Order: 1076-01-2013

Chris Sharp, A&P: 2755348AP

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
HC-C3YR-1RF/F7693F
PROP S/N: PA582B
REG. NO: N20GU
WORK ORDER:
1222-05-2014

Barber Aviation
4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 6/4/2014
A/C TSN: 2317.05
PROP TT: 99.3
TSPOH: 99.3
TACH: 2317.04

Prop Entries

(3) Complied with 100hr inspection per FAR43(app d). Dressed propeller blades.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1222-05-2014, Dated 6/4/2014.

DATE: 6/4/2014

SIGNED: 

Work Order: 1222-05-2014

Chris Sharp, A&P: 2755348AP

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
HC-C3YR-1RF/F7693F
PROP S/N: PA582B
REG. NO: N20GU
WORK ORDER:
1687-09-2017

Barber Aviation
4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 10/1/2017
A/C TSN: 2640.43
PROP TT: 422.68
TSPOH: 422.68
TACH: 2640.42

Prop Entries

(3) Complied with 100hr inspection per FAR43(app d). Dressed propeller blades.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1687-09-2017, Dated 10/1/2017.

DATE: 10/1/2017

SIGNED: 

Work Order: 1687-09-2017

Chris Sharp, A&P: 2755348AP

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
HC-C3YR-1RF/F7693F
PROP S/N: PA582B
REG. NO: N20GU
WORK ORDER:
1858-08-2018

C AND T Aviation INC
4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 9/18/2018
A/C TSN: 2742.53
PROP TT: 524.78
TSPOH: 524.78
TACH: 2742.52

Prop Entries

(3) Complied with 100hr inspection per FAR43(app d). Dressed propeller blades.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1858-08-2018, Dated 9/18/2018.

DATE: 9/18/2018

SIGNED: 

Work Order: 1858-08-2018

Chris Sharp, IA: 2755348AP

Printed by EBis 3 (datcomedia.com)

Date

PROP MODEL:
HC-C3YR-1RF/F7693F
PROP S/N: PA582B
REG. NO: N20GU
WORK ORDER:
2019-09-2019

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 10/7/2019
A/C TSN: 2831 58
PROP TT: 614 23
TSPOH: 614 23
TACH: 2831 57

atives,
pections.

Prop Entries

(3) Complied with 100hr inspection this date per FAR43(app d). Dressed blades.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2019-09-2019, Dated 10/7/2019.

DATE: 10/7/2019

SIGNED

Work Order: 2019-09-2019

Chris Sharp, IA: 2755348AP

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
HC-C3YR-1RF/F7693F
PROP S/N: PA582B
REG. NO: N20GU
WORK ORDER:
2189-11-2020

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 12/8/2020
A/C TSN: 2892 7
PROP TT: 674 95
TSPOH: 674 95
TACH: 2892 69

Prop Entries

(3) Complied with 100hr inspection this date per FAR43(app d). Dressed blades.

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2189-11-2020, Dated 12/8/2020.

DATE: 12/8/2020

SIGNED

Work Order: 2189-11-2020

Chris Sharp, IA: 2755348AP

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
HC-C3YR-1RF/F7693F
PROP S/N: PA582B
REG. NO: N20GU
WORK ORDER:
2378-12-2021

C AND T Aviation INC

4130 Aviation Drive
Madera, ca 93637
Phone: 559-675-0183

DATE: 3/9/2022
A/C TSN: 2954 07
PROP TT: 736 32
TSPOH: 736 32
TACH: 2954 06

Prop Entries

(3) Complied with 100hr inspection this date per FAR43(app d).

Maintenance Release

The aircraft and/or component(s) on N20GU was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2378-12-2021, Dated 3/9/2022.

DATE: 3/9/2022

SIGNED

Work Order: 2378-12-2021

Chris Sharp, IA: 2755348AP

Printed by EBis 3 (datcomedia.com)

SKY
TRAILS
AVIATION

Sky Trails Aviation | 2400 Rickenbacker Way | Auburn | CA | 95602
Date: 04-21-2023 Logbook: Propeller 1 Tail Number: N20GU

Tach: 3029.27 PTT: 811.53 Model: HC-C3YR-1RF / F7693F Serial: PA582B

Propeller: The aircraft propeller identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below.

Repairs / Maintenance



Blended nicks in propeller blades.

I certify that this Propeller was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition.

Signature:

Robert J. Burnett | AP 3633440 I.A.

Page 2

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			Sky Trails Aviation 2400 Rickenbacker Way Auburn CA 95602 Date: 07-01-2024 Logbook: Propeller 1 Tail Number: N20GU Tach: 3056.88 PTT: 839.14 Model: HC-C3YR-1RF / F7693F Serial: PA582B Propeller: The aircraft propeller identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below. Repairs / Maintenance • Profiled propeller blades. Lubricated hub with Aeroshell Grease #6. I certify that this Propeller was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition. Signature:  Robert J. Burnett AP 3633440 I.A.
			09/01/2025  Sky Trails Aviation 2400 Rickenbacker Way Auburn CA 95602 Date: 08-26-2025 Logbook: Propeller 1 Tail Number: N20GU Tach: 3117.85 PTSOH: N/A PTE: 900.11 Model: HC-C3YR-1RF / F7693F Serial: PA582B Propeller: The aircraft propeller identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work below. Repairs / Maintenance • Blend small nicks in propeller blades I certify that this Propeller was inspected in accordance with an Annual inspection and was determined to be in Airworthy condition. Signature:  Robert J. Burnett AP 3633440 I.A.